NASA CONTRACTOR REPORT 166503

(NASA-Ch-166503) DEMCNSTRATION ADVANCED AVIONICS SYSTEM (LAAS), PHASE 1 Final Contractor Report (Honeywell, Inc.) lul p HC AOS/MF AOI Cause UID

N83-31602

Unclas G3/06 13309

Demonstration Advanced Avionics System (DAAS) Phase I

A.J. Bailey

D.G. Bailey R.J. Gaabo

R.G. Lahn

J.C. Larson E.M. Peterson

J.W. Schuck

D.L. Rodgers K.A. Wroblewski



CONTRACT NAS2-10021 April 1981



NASA CONTRACTOR REPORT 166503

Demonstration Advanced Avionics System (DAAS)
Phase I

A.J. Bailey

D.G. Bailey

R.J. Gaabo

T.G. Lahn

J.C. Larson

E.M. Peterson

J.W. Schuck

Honeywell, Inc. Minneapolis, Minnesota

D.L. Rodgers K.A. Wroblewski

King Radio Corporation Olathe, Kansas

Prepared for Ames Research Center Under Contract NAS2-10021



tional Aeronautics and Space Administration

Ames Research Center Moffett Field. California 94035

TABLE OF CONTENTS

Section		Page
1	INTRODUCTION	1
2	DEMONSTRATION ADVANCED AVIONICS SYSTEM (DAAS)	5
	2.1 DAAS Functional Description 2.1.1 DAAS Functions 2.1.2 DAAS Controls and Displays 2.1.3 DAAS System Architecture 2.2 DAAS Hardware Description 2.2.1 Computer Control Unit (CCU) 2.2.2 Integrated Data Control Center (IDCC) 2.2.3 Electronic Horizontal Situation	5 8 13 15 17 30 36
	Indicator (EHSI) 2.2.4 DAAS Radio Adapter Unit (RAU) 2.3 DAAS Operational Evaluation 2.3.1 Summary of Results 2.3.2 Simulator Description 2.3.3 Pilot Evaluations 2.3.4 Evaluation Procedure 2.4 Failure Mode and Effects Analysis (FMEA) 2.4.1 DAAS System Description 2.4.2 Assessment of Compliance with FAR	39 44 44 48 54 67 69
	Requirements 2.4.3 DAAS Failure Modes and Effects Analysis Results	77
3	PROJECTED ADVANCED AVIONICS SYSTEM (PAAS)	89
	3.1 PAAS System Description 3.1.1 PAAS Sensor Configuration 3.1.2 PAAS Data Bus 3.1.3 PAAS Computer Architecture 3.1.4 PAAS Displays 3.1.5 PAAS Servo Mechanization 3.1.6 PAAS Power Mechanization 3.1.7 PAAS Redundancy Management 3.2 PAAS Reliability Analysis 3.3 PAAS Cost Analysis 3.4 PAAS Maintainability Analysis 3.5 PAAS Modularity Analysis 3.5 PAAS System Modularity	89 91 95 96 98 98 99 106 111 114 115

TABLE OF CONTENTS (Concluded)

Section		
3.5.3 PAAS Hardware Modularity 3.5.4 PAAS Software Modularity	119 121	
4 CONCLUSIONS AND RECOMMENDATIONS	122	
4.1 Functional Capability 4.2 Cost 4.3 Reliability, Safety 4.4 Maintainability 4.5 Modularity	123 125 126 127 127	
GLOSSARY	129	
APPENDIX A - PROFILES OF DÁAS TEST PARTICIPANTS	733	
APPENDIX B - DAAS FAILURE MODES AND EFFECTS ANALYSIS	136	

LIST OF ILLUSTRATIONS

Figure		Page
2-1	Cessna 402B Control Panel Layout	9
2-2	DAAS System Architecture	14
2-3	DAAS System Diagram	16
2-4	DAAS Flight Hardware	18
2-5	DAAS Central Computer Unit	19
2-6	DAAS Central Computer Unit Installation Drawing	21
2-7	DAAS Processor Module	22
2-8	DAAS Bubble Memory System	24
2-9	DAAS Integrated Data Control Center (IDCC)	31
2-10	IDCC Installation Drawing	32
2-11	DAAS Electronic Horizontal Situation Indicator (EHSI)	37
2-12	EHSI Installation Drawing	38
2-13	DAAS Radio Adapter Unit (RAU)	40
2-14	DAAS Simulator	45
2-15	Simulator Hardware Interfaces	52
2-16	Evaluation Scenario Chart (Minneapolis Local Victor Airway Chart)	59
2-17	Minneapolis-St. Paul International RNAV Rwy 29 Right	63
2 1	DAAS Suctom Architecture	90

LIST OF ILLUSTRATIONS (Concluded)

Figure	•	Page
3-2	Skewed Sensor Geometry	93
3-3	PAAS Panel Concept	97
3-4	PAAS Manual Redundancy Management	100
3-5	PAAS Maintenance Concept	112
3 - 6	PAAS Modularity	116
3-7	DAAS Processor Module	120

LIST OF TABLES

<u>Table</u>		Page
2-1	NAVAID Data for Evaluation Scenario	61
2-2	Waypoint Data for Evaluation Scenario	62
2-3	DAAS Elements Failure Rates	79
2-4	Summary of the DAAS Failure Modes and Effects Analysis	83
2-5	Failure Categorization of the DAAS Elements	87
3-1	Reliability Estimate for a Conventional System	101
3-2	Reliability Estimate for PAAS	104
3-3	Cost Estimate for a Conventional System	107
3-4	Cost Estimate for PAAS	109

SECTION 1 INTRODUCTION

General Aviation serves an important role in transportation and in the Nation's economy. But operating procedures are complicated, regulations are restrictive, and the demands of the National Air Traffic Control (ATC) system are increasing. All of these factors contribute to an increasing dependence on avionics and to a corresponding increase in their cost and complexity. Furthermore, such diverse considerations as safety, rising fuel costs, and the desire to improve single pilot IFR operation will stimulate the demand for even more avionics.

To date, the avionics industry has been able to meet the increasing requirements for avionics at affordable prices by aggressively applying new technologies. The application of new technology has been along traditional lines, however, with integration occurring only in a few specific areas such as navigation/communication systems and integrated flight director/autopilot designs. this approach, the addition of more sophisticated capabilities -such as a performance computer, a pilot alert system, or a groundproximity warning system -- is expensive and cumbersome because of the need for separate computers, separate displays and controls, and signals from aircraft sensors that either do not have an appropriate output, or are not easily accessible. However, as a result of recent developments in microprocessors, busing, displays, and software technology, it may be possible to configure an integrated avionics system that is better suited for accommodating these future requirements.

In 1975, a research and development program was initiated within the National Aeronautics and Space Administration to determine the feasibility of developing an integrated avionics system suitable for general aviation in the mid-1980s and beyond. The objective was to provide information required for the design of reliable integrated avionics. This avionics was to provide expanded functional capability that would significantly enhance the utility and safety of general aviation at a cost commensurate with the general aviation market.

The program has emphasized the use of a data bus, microprocessors, electronic displays and data entry devices, and improved function capabilities. As a final step, a Demonstration Advanced Avionics System (DAAS) capable of evaluating the most critical and promising elements of an integrated system will be designed, built, and flight tested in a twin-engine general aviation aircraft.

A contract was awarded to Honeywell, Inc., teamed with King Radio Corp., in August 1978 for the design and fabrication of DAAS. The specific objectives were (1) to fabricate an integrated avionics system based on the information obtained in the investigations described in the foregoing paragraph (2) to incorporate in this system a set of functional capabilities that will be beneficial to general aviation, and (3) to design the displays and controls so that the pilot can use the system after minimum training. The system will be installed in the Ames Research Center's Cessna 402B in the early part of 1981; engineering flight testing will begin at King Radio in Olathe, Kansas, in mid-1981. Flight tests at Ames Research Center are expected to start in late 1981. During the flight tests, guest pilots from various segments of the general aviation community will be invited to evaluate the DAAS concept.

The DAAS Program also includes definition and analysis of a projected Advanced Avionics System (PAAS). PAAS extrapolates the DAAS concept of integrated, fault tolerant avionics to a potential operational version for the mid-1980s. PAAS was analyzed to determine reliability, cost, etc., and impact of the DAAS concept in comparison to conventional architecture. The results are contained herein.

This report documents the DAAS Program Phase I System Design, and includes the following:

- DEMONSTRATION ADVANCED AVIONICS SYSTEM (DAAS)
 - DAAS Functional Description
 - DAAS Hardware Description
 - DAAS Operational Evaluation
 - DAAS Failure Modes Effects Analysis
- Project Advanced Avionics System (PAAS)
 - PAAS Description
 - PAAS Reliability Analysis
 - PAAS Cost Analysis
 - PAAS Maintainability Analysis
 - PAAS Modularity Analysis
- Conclusions and Recommendations

Additional detailed design information is contained in the following documents:

- 'Demonstration Advanced Avionics System (DAAS) Functional Description,' 15 October 1980, NASA CR-152405, by Honeywell Inc. and King Radio for Ames Research Center, NASA.
- 'DAAS-System Specification (YG 1210),' 20 December 1979, Honeywell Specification DS 28150-01.
- 'DAAS Central Computer Unit (BG1135),' 3 October 1980, Honeywell Specification DS 28151-01.
- 'EHSI (Electronic Horizontal Situation Indicator) JG12D4AA,' 13 December 1979, Honeywell Specification D538153-01,
- 'IDCC (Integrated Display and Control Center), DAAS HG1052AA,' 13 December 1979, Honeywell Specification DS28154-01.
- 'NASA-Honeywell DAAS Radio Adapter Unit P/N 066-1083-00,'
 14 September 1979, King Radio Corp. Specification 001-5018-00.
- 'Software Development Specification For Y61210 NASA DAAS Avionics System,' Honeywell Specification DS28152-01.

SECTION 2 DEMONSTRATION ADVANCED AVIONICS SYSTEM (DAAS)

DAAS is the demonstrator system intended to physically demonstrate the characteristics of a fault telerant integrated avionics system in a Cessna 402B aircraft. Following is description of the demonstrator system including functional description, hardware description, documentation of the DAAS operational evaluation conducted on the DAAS simulator, and documentation of the failure modes and effects analysis conducted to verify DAAS flight safety.

2.1 DAAS FUNCTIONAL DESCRIPTION

The DAAS is an integrated system. It performs a broad range of general aviation avionics functions using one computer system, and shared controls and displays. Following is brief description of the DAAS functions, controls and displays, and DAAS architecture.

2.1.1 DAAS Functions

- <u>Autopilot</u> The autopilot is a digital version of the King KFC200 modified for compatibility with DAAS. The basic autopilot modes are:
 - Yaw Damper
 - HDG SEL (Heading Select)
 - ALT, ALT ARM (Altitude Hold, Altitude Arm)

- NAV, VNAV Coupled Control
- Approach Coupled Control
- Navigation/Flight Planning The navigation/flight planning function computes aircraft position with respect to an entered flight plan, and blends dead-reckoning position (as determined from airspeed and heading) with position extracted from automatically tuned VOR/DME receivers. Functions are:
 - 10 Waypoints, 10 NAVAID Storage
 - Kalman Filter Blending
 - Moving Map Display
- Flight Warning/Advisory System DAAS includes extensive monitoring, with warning capability. For example, the DAAS system monitors engine performance (MAP, RPM), aircraft configuration (gear position, flap position, etc.) with respect to flight condition, and ground proximity and informs the pilot of undesirable situations. Monitoring includes:
 - Engine Parameter Monitoring Warning
 - Aircraft Configuration Monitoring, Warning
 - Airspeed and Stall Monitoring, Warning
 - Altitude Advisory Function
 - Marker Beacon Advisory Function
 - NAVAID Identification Monitoring
 - Autopilot/Flight Director Monitoring
 - BIT Fault Warning

- GMT Clock Function The DAAS computer serves as a GMT clock.
- Fuel Totalizer Function Fuel flow is integrated to totalize fuel used.
- Weight and Balance Computations Weight and balance, and takeoff cruise performance calculations can be quickly and conveniently performed using DAAS controls and displays.
- Performance Computations The DAAS system will determine fuel and time required to fly specific segment distances given altitude, temperature, wind data, and engine power setting. Performance computation functions are:
 - Takeoff Performance
 - Cruise Pertormance
 - Fuel/Distance/Time Computation
- DABS (Discrete Address Beacon System) ATC Communication, Weather Reporting ATC text messages (e.g., CLIMB AND MAIN-TAIN 1200 FT) or weather information at destination can be communicated to the DAAS pilot via DABS data link and displayed on the DAAS electronic display.
- BIT (Built-in Test) The DAAS system will detect and localize its own faults via BIT. Provisions are also included for troubleshooting the DAAS hardware through DAAS controls and electronic displays.

• Normal, Emergency Checklists - Normal and emergency checklists are stored in the DAAS computer, and are available for display at the push of a button.

These functions are managed via shared controls and displays, and performed in the common DAAS computer system.


2.1.2 DAAS Controls and Displays

The DAAS Cessna 402B aircraft contains --

- Controls and displays necessary to manage DAAS functions.
- Additional instruments necessary for IFR flight operations.
- Independent safety pilot instrument installation.

These controls and displays are layed out in the 402B control panel as indicated in Figure 2-1, Cessna 402B Layout. The DAAS pilot is in the left seat, and the safety pilot in the right seat. Electronic displays — the Electronic Horizontal Situation Indicator (EHSI) and Integrated Data Control Center (IDCC) — are key elements of the panel.

The EHSI presents a moving map display showing aircraft position with respect to desired course. The display is a 4.5-inch monochromatic Ball Brothers 103C CRT raster display unit. The display unit has 256- by 256-dot matrix display capability. P43 phosphor is used together with an appropriate narrow band optical filter to allow operation in bright sunlight. The EHSI is controlled by functional control buttons and a map slew controller.



ORIGINAL PAGE IS OF POOR QUALITY

The Integrated Data Control Center (IDCC) is the pilot's primary means of interacting with DAAS. Included are a keyboard at the bottom of the unit and a set of function buttons along the top. The function buttons include a set of page select buttons which determine the information that is displayed on the IDCC display.

The IDCC display CRT is identical to the EHSI; i.e., 4.0-inch by 4.5-inch Ball Brothers monochromatic unit. The IDCC can display 16 lines of 32 characters each. Line spacing is 0.25 inch, character height is 0.162 inch, and character width is 0.125 inch.

The IDCC is implemented with menu select buttons along each side of the CRT, or with a pressure sensitive plastic screen overlay for touch point menu selection. The alternate approaches can be implemented to allow comparison during flight test.

The DAAS EHSI is surrounded by the conventional "T" pattern of flight control instruments.

The ADI used in DAAS is the 4-inch King KCI 310 Flight Command Indicator.

The altimeter is an IDC Encoding Altimeter type 519-28702-571. An altitude alert light is mounted on the altimeter.

The rate-of-climb indicator provides vertical speed information to the pilot. The display presents rates of climb, or descent, in feet per minute. The face is 2-1/4 inches wide.

The King KI 226 RMI displays heading and bearing to a selected VOR station.

ORIGINAL PAGE IT

The DAAS Autopilot Mode Controller is located on the pedestal, and the Autopilot Mode Annunciator is located above the altimeter.

DAAS engine instruments and radio stack are centrally located and are accessible to the DAAS pilot and the safety pilot.

Unique DAAS switch controls located on the panel include:

- NAV 1-DAAS/MANUAL Tune (located to the right of the NAV 1 radio)
- NAV 2-DAAS/MANUAL Tune (located to the right of the NAV 2 radio)
- DME TRANSFER (located to the right of the DME)
- VOR source switch (located to the lower left of the RMI)
- ILS source switch (located to the lower left of the ADI)

NAV Receivers can be tuned manually (MANUAL) or automatically (DAAS). The DME transfer switch allows the DME receiver to be tuned by either NAV receiver 1 or 2. The DAAS position slaves the DME to the NAV receiver being controlled by DAAS.

The safety pilot instrument set is independent from the DAAS instruments, and adequate for safe flight with DAAS inoperative.

The safety pilot's Pictorial Navigation Indicator displays air-craft magnetic heading (gyro-stabilized), selected heading and selected course. Also, VOR and localizer course deviation, glideslope deviation and a TO-FROM indication are presented.

ORIGINAL PAGE IS OF POOR QUALITY

The safety pilot's KG-258 artificial horizon is an air driven unit. It is the safety pilot's basic attitude/horizon reference indicator.

Aircraft master power controls are centrally located overhead. Circuit breakers are located on the pedestal.

2.1.3 DAAS System Architecture

DAAS system architecture is presented in Figure 2-2. The architecture is characterized by a modular computer system structure; i.e., multimicroprocessors interconnected by an IEEE 488 data bus. Each processor block in Figure 2-2, except for the radio system, represents an Intel 8086 16-bit microprocessor, 2k by 16 PROM memory, and 4k by 16 to 16k by 16 RAM memory. The radio System uses the Intel 8048 microprocessor.

Each processor performs a function, and interfaces directly with the subsystems associated with that function. At power-on, the bus controller Computer CPU-1 takes functional programs from the nonvolatile bubble memory, and sequentially loads each processor at the rate of approximately 2 seconds per processor. When all processors are loaded, the bus controller activates the system. The bus controller then manages bus communications during normal operations.

A portable TI Silent 700 cassette unit can interface with the bus controller to allow load or modifications of the functional software.

CC-CPU 5 is a spare processor. If processor CC-CPU 3 or CC-CPU 4 fails and the bus controller detects the failure,




Figure 2-2. DAAS System Architecture

ORIGINAL PAGE IS OF POOR QUALITY



the bus controller will load CC-CPU 5 with appropriate software from bubble memory, and CC-CPU 5 will take over the function of the failed processor. (Note: This reconfiguration capability is especially important when an EHSI and an EADI are included in the PAAS system. With a failure in one display, the spare processor could be loaded to allow time sharing of the remaining good display as both EADI and EHSI.) Such reconfiguration could be extended to other processors such as CC-CPU 2, the autopilot. However, for such reconfiguration the spare processor must interface with autopilot subsystems, which requires additional multiplexing of hardware. Reconfiguration was thus applied only to a limited degree in this demonstrator system.

The DAAS architecture is modular. Functions can be added by adding necessary standard processor modules onto the 488 data bus, and interfacing these processor modules with the devices associated with the new function.

Six processors are contained in the DAAS Central Computer Unit. One processor is contained in the IDCC, and one processor is contained in the radio adapter unit.

2.2 DAAS HARDWARE DESCRIPTION

DAAS system components, and their interconnections are depicted in Figure 2-3, DAAS System Diagram. Interconnection between the DAAS panel instruments, sensors, and the DAAS computer system is shown. The DAAS Central Computer obtains data from the radio system (radio adapter unit, radio stack), flight control sensors, engine instruments, configuration status sensors, and IDCC.




Figure 2-3. DAAS System Diagram

OTHER PART TO OF POOR QUALITY

Functional computations are performed on the input data and the results applied to EHSI, FDI, warning/caution lights, and autopilot servos.

Following is a description of new design DAAS flight hardware including:

- Central Computer Units
- IDGC
- EHSI
- Radio Adapter Unit

The hardware is shown in Figure 2-4.

2.2.1 Computer Control Unit (CCU)

The CCU, Figure 2-5, consists of the following computer processing units (CPUs) and their associated I/O interfaces:

- Autopilot CPU
- Bus Controller CPU
- EHSI CPU
- NAV CPU
- DABS CPU
- Spare CPU

In addition, the CCU contains a one mega-bit bubble memory and the regulated power supplies for the DAAS system.

2.2.1.1 <u>Mechanical</u> -- The CCU is packaged in a full ATR Chassis. The dimensions of which are given in the installation drawing



Figure 2-4. DAAS Flight Hardware. From left to right: Electronic Horizontal Situation Indicator, Central Computer Unit, Radio Adapter Unit, and Integrated Data Control Center.




Figure 2-5. DAAS Central Computer Unit

shown in Figure 2-6. The chassis has been constructed to accept up to twenty-three 6.25 by 6.25 inch card assemblies plus four larger 10 by 6 inch card assemblies. All interconnections of the card assemblies are via a wirewrap mother board.

2.2.1.2 <u>CPU and Memory</u> -- Each CPU has been designed to fit on a single printed circuit board card assembly as shown in Figure 2-7. A CPU consists of the 8086 microprocessor, 4K by 16 of RAM memory, 2K by 16 of UV-EPROM, an 8259 programmable interrupt controller, and the IEEE-488 bus interface circuitry. In addition to the 8086 microprocessor IC, the processor also contains an 8284 clock generator, bus buffer logic, and memory chip select logic.

To facilitate software development, the 8086 is mounted in a quick-eject socket. This allows easy replacement of the 8086 with an in-circuit emulator (ICE-86). The 8086 is operated at 4 MHz by driving the clock generator with a 12 MHz crystal. This clock frequency was selected to be comptaible with the ICE-86 which has a maximum limit of 4 MHz.

The 8259 programmable interrupt controller provides the capability for eight vectored interrupts. The IEEE-488 bus utilizes the highest priority interrupt with the rest of the interrupt lines connected to special functions associated with each processor.

The IEEE-488 bus interface is implemented with 9914 GPIB adapter and two bus transceiver ICs. The 9914 is a 40-pin LSIC that can be programmed to be a talker/listener or as a bus controller while meeting all of the requirements of IEEE-488. This feature of the 9914 allowed all of the CPUs to be designed identically. Communication between the 8086 and the 9914 is carried out via memory




Figure 2-6. DAAS Central Computer Unit Installation Drawing




Figure 2-7. DAAS Processor Module

mapped registers. There are 13 registers within the 9914, 6 of which read and 7 write. These registers are used both to pass commands or data to, and to get status or data from, the device.

There are 4K of RAM memory and 2K of UV-EPROM available on the CPU card assembly. An additional 4K or 8K of RAM memory is available with the memory expansion card assemblies. Memory expansion card assemblies are provided for the autopilot, EHSI, NAV, and spare CPUs. Also provided on the memory expansion card assemblies is the I/O address decoding logic associated with that CPU. From a software standpoint, all of the I/O addressing is treated as memory mapped.

2.2.1.3 CCU Bubble Memory System -- A Rockwell bubble memory system is used for the nonvolatile storage of the CPU software programs. The bubble memory system, Figure 2-8, consists of two card assemblies, a 1-megabit memory assembly (RLM 658), and a controller assembly (RCM 650). The RLM 658 assembly provides the 1-megabit of storage via four 256K-bit (RBM 256) devices which are operating in parallel. The RLM 658 also contains the sense amplifiers, coil drivers, operator logic (transfer, replicate and generate pulses), and the chip mapping PROM. The chip mapping PROM contains the redundancy information on the good and bad loops in each of the REm 256 devices. The RCM 650 controller organizes the memory to appear as an 8-bit byte parallel operation with 128-byte blocks. Thus the memory is addressed by blocks (1 to 1024) with 128 bytes per block. The RCM 650 uses a preprogrammed 6502 microprocessor to accomplish the controller functions. Also, included on the RCM 650 is a 1k by 8 buffer memory which is the main interface between the bus controller CPU and the bubble memory.




Figure 2-8. DAAS Bubble Memory System

ORIGINAL FACT IN

- 2.2.1.4 <u>CCU Cassette Interface</u> Tape cassettes are used for initially loading the bubble memory with the software programs for all of the CPUs. A PROM program in the bus controller CPU, allows the bus controller to read the ASCII data from the cassette, convert it to binary, and transfer the binary data to the bubble memory. A standard RS-232 interface is used between the bus controller CPU and the ASR733 data terminal with dual cassettes. This RS-232 interface, along with additional bubble memory address decoding, is contained on the cassette and bubble memory I/O card assembly.
- 2.2.1.5 <u>Display Controller</u> -- Two ALT 512 graphics display controllers are used to generate the video signal for the EHSI. Each ALT 512 contains its own 131,021-bit refresh memory, TV sync, and video generator. The display field for each ALT 512 consists of two 256 by 256 by 1 planes. The two-plane arrangement allows eight different display formats. The mode of operation selected for the EHSI is to display one plane while the EHSI CPU erases and updates the other plane. Two ALT 512s are required to increase the throughput on the EHSI. The display information that requires faster updating is programmed in one of the ALT 512s while the slower information, which is updated at a slower rate, is programmed in the other ALT 512. The two ALT 512s are operated with one as the master, and the other as the slave (i.e. the slave receives its video clock and sync timing from the master). The combined video output is then transmitted to the EHSI CRT monitor.

The ALT 512 utilizes a standard S-100 bus for all of the I/O interfaces. In order to provide the reconfiguration capability of letting either the EHSI CPU or the spare CPU drive the EHSI, the multiplexing of the address, data, and control lines from these CPUs to the ALT 512s must be provided. This multiplexing

circuitry is provided on the memory expansion cards associated with those CPUs. Control of which CPU is driving the EHSI comes as a discrete output from the bus controller CPU.

2.2.1.6 <u>CCU DABS Interface</u> -- Both the standard message (SM) interface and the extended length message (ELM) interface have been implemented for communication between the DABS transponder and the DABS CPU. The SM interface consists of a gated clock controlled by the transponder, and a bidirectional data line for serial transmission of data. For up-linking of information, data received from the transponder is converted from serial to parallel and stored in a 16 by 8 buffer memory. Upon receipt of a complete COMM-A message, an interrupt is generated to the DABS CPU which causes this CPU to read the contents of the buffer memory. For down-link information, the reverse process is required. The DABS CPU loads a 16 by 8 buffer memory and then sets the B-bit in the SM interface format. Upon receipt of a COMM-B message to the transponder, the data is converted from parallel to serial and transmitted to the transponder.

The ELM interface is a full duplex, synchronized serial binary data interface in accordance with RS-449. The following interface circuits are provided:

- ST send timing (from transponder)
- SD send data (to transponder)
- RS request to send (to transponder)
- CS clear to send (from transponder
- RT receive timing (from transponder)
- RD receive data (from transponder)

ORIGINAL PAGE IS OF POOR QUALITY

- DM data mode (from transponder)
- IS terminal in service (to transponder)

All of these interface circuits are bipolar, balanced circuits that operate at voltage levels and impedance levels as specified in RS-422. Operation of the ELM interface is similar to the SM interface except that the buffer memory is 256 by 8. This allows 16 COMM-C or COMM-D segments to be received or transmitted as a block respectively. The transponder takes care of all the COMM-C and COMM-D decoding and downlink message initiation. The circuit-ry required to implement the SM and ELM interfaces is contained on the DABS SM card assembly and the DABS ELM card assembly.

- 2.2.1.7 <u>CCU I/O Interface</u> -- With the exception of the previously discussed interfaces, all of the I/O devices (aircraft sensors, engine monitors, mode control panels, etc.) interfaces directly with the autopilot CPU. This I/O interface provides the capability for:
 - 48 discrete inputs
 - 48 discrete outputs
 - 64 analog inputs
 - 16 analog outputs

CCU Discrete I/O -- The discrete inputs are multiplexed into 4 words of 12 bits each before being read by the autopilot CPU. One of the discrete input words is reserved for self test (wraparound) of the flight critical discrete outputs. Each discrete input is signal conditioned and prefiltered (0.8 msec. time constant) before being multiplexed to a comparator to determine its logic state.

The discrete outputs are organized into 3 words of 16 bits each. The discretes are stored in three 16-bit registers which are written into directly from the autopilot CPU. The outputs of these registers are buffered with high voltage open collector drivers, thus providing either an open or ground. The majority of the discretes are used for annunciation and the drivers tie directly to 28-volt lamps. The autopilot clutch engage and the auto-trim discretes require additional drive capability. This is provided with a discrete transistor stage added to the regular drivers.

The discrete input circuitry and the discrete output circuitry for 16 of the outputs is contained on the discrete I/O card assembly. The circuitry for the rest of the discrete outputs including the special drivers is contained on the discrete output card assembly. The real-time clock is also included on this card assembly. The real-time clock is a counter running from the autopilot CPU Crystal Controlled Clock. It generates an interrupt 40 times per second to the autopilot, NAV, IDCC, and spare CPUs.

CCU Analog Inputs -- Four DG 506 16-channel multiplexers are utilized to allow up to 64 analog inputs to be multiplexed to a 12-bit (11 bits + sign) A/D converter. Each analog input is signal conditioned, scaled, and prefiltered prior to the multiplexer. The AC signals are demodulated using an LF 198 sample-hold IC with the sampling synchronized to occur at the peaks. A frequency to voltage converter is used for signal conditioning of the true airspeed signal.

The A/D converter and 32 channels of multiplexing are contained on the ADC and MUX card assembly. The A/D converter is a

successive approximation type converter with a conversion time of 32 microseconds, including multiplex and settling time. The converter is composed of a 562 type D/A converter and two 8-bit 2503 successive approximation registers. The input scaling is setup such that ±10 volts at the input to the A/D converter corresponds to full range. The additional 32 channels of multiplexing is contained on the DC Inputs and MUX card assembly.

Also contained on this card assembly is the signal conditioning (differential buffer amplifiers and prefilters) for the do inputs. The ac input card assembly contains a Scott-T transformer for converting the heading synchro signals to sin and cosine, second-order prefilters for the pitch and roll attitude signals, and the demod amplifiers for converting these ac signals to dc. The yaw servo amplifier, the pitch and roll command bar amplifiers, the VNAV deviation indicator drive circuitry, and the true airspeed frequency to voltage converter are also contained on this card assembly.

CCU Analog Outputs -- Each analog output consists of an LF 198 sample-hold which is updated from a 12-bit D/A converter. Of the 16 analog outputs provided, 8 are used for inflight recording, 3 for the pitch, roll, and yaw servo amplifiers, 1 each for pitch command bar, roll command bar, and VNAV deviation, and the other two are spares. The D/A converter is a 562 type that is operated in the bipolar mode with a signal range of ±10 volts. The D/A converter, 16 sample-holds, 16-channel decoding, and the pitch and roll servo amps are all contained on the DAC and Servo Amp card assembly.

2.2.1.8 <u>CCU Power Supplies</u> -- All power for the CCU and the IDCC is generated from the aircraft +28 Vdc bus. An Abbott BN1000

power module is used for the +5-volt supply. This dc-to-dc converter uses a pulse width modulated inverter switching at 18 to 20 kilohertz to achieve an efficiency up to 70 percent with output capability to 20 amps. Similarily, an Abbott BBN500 power module provides a dual output ±15-volt supply. This supply has an output current capacity of 1.67 amps on each output. The bubble memory and the ALT-512 require ±12 V dc which is supplied from a linear regulator operating from the ±15-volt supplies. All of these supplies require approximately 10 amps from the 28-volt bus.

2.2.2 Integrated Data Control Center (IDCC)

The IDCC, Figure 2-9, consists of two basic assemblies: the CRT monitor assembly, and the chassis assembly. The over-all dimension of the IDCC are shown in Figure 2-10. The CRT monitor assembly is mounted in the IDCC chassis assembly which, in turn, is mounted in the aircraft.

2.2.2.1 <u>CRT Monitor Assembly</u> -- The CRT monitor assembly is a standard, solid state, monochromatic television monitor designed for avionics display applications. The monitor is 7.7 inches wide, 6.0 inches high, by 11.0 inches deep. It is a raster type monitor capable of 525 lines with a 2:1 interface at 30 frames per second, or a non-interlaced 262-line field at 60 fields per second. The latter is used in this application. The monitor is designed with P-43 phosphor and a narrow bandpass optical filter to produce a sunlight readable display. The display area is 4.5 by 4.5 inches.

2.2.2.2 <u>IDCC Chassis Assembly</u> -- The IDCC chassis assembly contains the following subassemblies in addition to the CRT assembly:

ORIGINAL PASE IS OF POOR QUALITY




Figure 2-9. DAAS Integrated Data Control Center (IDCC)

ω 2

Figure 2-10. IDCC Installation Drawing

- CPU and memory
- Keyboard
- Pushbutton switches
- Touchpoint switches
- Miscellaneous controls

IDCC CPU and Memory -- The IDCC contains its own central processing unit (CPU) and associated memory. The CPU is an 8086 - 16-bit microprocessor. The memory consists of 16K by 16-bit RAM and 2K by 16 bit ROM. The RAM is used for both program memory and scratchpad memory, and the ROM is used to store the initial-ization programs. The CPU, together with 4K of RAM and the bus interface circuitry, is packaged on one card. A second card contains 8K of RAM. A third card contains 4K of RAM. The fourth card contains the CRT refresh memory and the I/O circuitry.

The CPU, together with its memory, performs the following functions:

- Message storage.
- Message formatting.
- Output of messages to display refresh memory.
- Scanning of switches and touchpoints.
- Outputting and receiving intercommunications with the Central Computer Unit over the IEEE 488 bus.

IDCC CRT Refresh Memory -- Since the CRT monitor has no memory, it must be re-refreshed at the 60-Hz field rate. A CRT controller circuit is used to accomplish this function. This circuit accepts data from the CPU defining the alpha-numeric characters to be

displayed on the CRT display. It then outputs the appropriate video signals to the monitor to display these characters at the 60-Hz field rate. The display field consists of 16 lines of 32 characters.

IDCC Switch Scanning -- The IDCC provides for scanning of the switches and touchpoints on the IDCC as well as the switches on the EHSI. The switches on the IDCC consist of the pushbutton switches (mode and page select) located across the top of the IDCC, the keyboard switches, the forward and back page switch, the message acknowledge switch, and the light touchpoints. The switches on the EHSI consist of the nine switches used for EHSI control, and the eight switches used for slewing the display and cursor. The switches are scanned and debounced using IC hardware. The results of the scanning are entered into the CPU via memory mapped I/O and vectored interrupts.

IDCC Keyboard -- The IDCC keyboard is mounted at the lower left corner of the IDCC. It projects outward and downward at approximately a 30-degree angle for ease of operation. The keyboard consists of 20 keys arranged in a four horizontal by five vertical matrix.

It should be noted that the keyboard has full alpha-numeric capability. Numeric entry requires only pressing one key. Alpha entries, however, require two key entry. Each key has three alpha characters in addition to the one numeral. The alpha characters are entered by first pressing the key with the triad of alpha characters that includes the desired character and then pressing one of the post designation keys, in the bottom row, to select left, middle, or right alpha character of the triad.

The keyboard is back lighted for night operation.

<u>Pushbutton Switches</u> -- The IDCC has 18 pushbutton switches located across the top to the unit. In the current mechanization, 14 of the 18 pushbuttons are used.

The pushbuttons are backlighted for night operation. One pushbutton (AUTO SEQ SEL) incorporates a green light indicator. The green light is on when the auto-sequence mode is on.

IDCC Touchpoints -- The IDCC incorporates touchpoints that are used to interact with the CRT display. There are eight touchpoints arranged in two vertical columns of four each. The touchpoint switches are implemented in two different configurations.

The normal touchpoint configuration is implemented with eight individual switches located in the bezel of the CRT display.

An alternate touchpoint configuration can be installed by removing the switch mounting bezel and replacing it with a plastic overlay. This overlay incorporates a touchpoint matrix that can be activated by finger pressure on the CRT face. The touchpoints in this configuration are also located in two columns of four each.

The two different configurations are electrically compatible and interface to the system thru a chassis mounted convertor.

IDCC 488 Bus Interface -- The IDCC communication with the central computer unit is over the IEEE 488 bus. The bus interface module (BIM) used in the IDCC is the same as that used in the central computer. It utilizes the TI 9914 488 bus controller IC.

IDCC Power Requirements — The CRT monitor portion of the IDCC requires 60 watts maximum of 28 volts de power, 28 VDC. The chassis portion of the IDCC requires approximately 2 amps of +5 volts de. The only other power required by the IDCC is the switch lighting power derived from the 28-volt de.

2.2.3 Electronic Horizontal Situation Indicator (EHSI)

The EHSI, Figure 2-11, consists of two basic assemblies - the CRT monitor assembly and the EHSI controls assembly. The overall dimensions of the EHSI are shown in Figure 2-12.

- 2.2.3.1 EHSI CRT Monitor Assembly -- The CRT monitor assembly is idential to the IDCC CRT monitor assembly. For a detailed description of the CRT monitor assembly refer to paragraph 2.1 of this report.
- 2.2.3.2 <u>EHSI Controls Assembly</u> The EHSI controls assembly consists of a face plate, nine pushbutton control switches, and a slew control switch subassembly.

EHSI Pushbutton Switches -- The current mechanization uses eight of the nine available pushbutton switches. The pushbutton switches are white lighted for night viewing. In addition, green lighting is provided for mode annunciation. The heading-up/north-up map orientation select switch and the map slew or cursor slew select switches are split legend annunciators. Either the top half or bottom half may be lighted green to indicate the mode selected. All other switches are full legend annunciations. Since the map return is a momentary mode, the green annunciator is not used on this switch.







Figure 2-11. DAAS Electronic Horizontal Situation Indicator (EHSI)



38

Figure 2-12. EHSI Installation Drawing

All switch actions are momentary. The mode latching is done in the IDCC CPU. As discussed in paragraph 2.2.2.2, these switches are scanned by the IDCC CPU. The IDCC CPU also controls the annunciator lighting.

EHSI Slew Control Switch -- The slew control switch consists of a single lever operating light switch. The lever is mechanically constrained so that either horizontal or vertical movement only is allowed. The lever is spring loaded to the center off position. The lever actuates one or two switches in each of the four directions, up, down, left, or right. The first switch activation causes a slow slewing effect, the second causes a fast slewing effect.

2.2.3.3 <u>EHSI Power Requirements</u> -- The CRT monitor portion of the EHSI requires 60 watts maximum, 28-volts dc power. The control switch portion requires only the signal level scanning power from the IDCC CPU. Nighttime lighting and annunciator lighting power for the switches is derived from the IDCC.

2.2.4 DAAS Radio Adapter Unit (RAU)

The following functions are performed by the RAU, Figure 2-13.

- Tune the radios as commanded by the DAAS computer
- Process VOR/LOC/CS data from NAV 2 and NAV 2
- Process station identifiers
- Process DME distance
- Generate a radio system status word
- Format the data for block transfer




Figure 2-13. DAAS Radio Adapter Unit (RAU)

- Exchange information with the DAAS computer via the IEEE 488 bus

In addition to interfacing with the radio units, the RAU also interfaces with --

- 28-V dc aircraft power
- KMA 24 audio panel (with KA 35A)
- KCI 310 ADI (through ILS source switch)
- KI 226 RMI (through the VOR source switch)
- DME channeling switch and ILS source switch
- DAAS/Manual status switch for each NAV receiver

The DAAS system RAU uses a microprocessor system for a flexible interface for control and data processing. The interface exchanges data on the 488 bus using standard talker/listener functions and handshaking protocol. Also, the system monitors the radios, retaining and refreshing a defined data block for the data exchange process.

The processor sends the proper tuning commands to the radios, processes the received position data and transfers this data in block format to DAAS. The data block transfers occur at a fixed rate of approximately 20 updates per second as required by the bus controller.

The radio adapter unit will exchange data over the IEEE 488 bus. A dedicated general purpose interface buffer (GPIB) will handle the standard talker/listener protocol for transferring data. Data will be stored in a buffer to eliminate slowing down the

processor. Bus setup time is \leq 45 μs and data transfer rate is < 15 μs per byte.

NAV 1 and NAV 2 provide a video composite with either VOR or LOC information modulated onto the 9960-Hz subcarrier. The interface circuit identifies what type of information is present, demodulates the composite, and digitizes the result. The VOR/LOC data from NAV 1 and NAV 2 can also be displayed on the KI 226 and the KCI 310 indicators. The specific display mode is a function of the status switches.

Glideslope information is also available from the KN 53 Navigation Receivers. The signal will be conditioned in the interface for digital conversion. The digitized data will then be processed and maintained in the data block for transfer to DAAS. As with VOR/LOC, glideslope information can also be displayed on the KCI 310 Indicator. The program will select the navigation unit to be displayed when in the DAAS mode.

To validate active channels of the navigation radios, the identifiers will be read electronically, converted to the ASCII equivalent of the received Morse code, and stored as part of the data block.

The similarity in tuning procedure for the KN 53 and KY 196 allows a common method of tuning these radios. The interface simulates the actions of the front panel rotary knobs by closing increment/ decrement switches electronically to change frequency. The standby frequency only is affected by the tuning switches. To change the active channel, standby is turned to the selected frequency, and an active/standby exchange is executed. The approximate worst case tuning time for a KY 196 or KN 53 to sweep full

band is 250 milliseconds. To execute an active/standby exchange, approximately 50 milliseconds is required. The hardware for tuning the KY 196 receivers is included in the RAU, but not the necessary software.

The KN 62A can be tuned by DAAS NAV 1 or NAV 2 through a common bus. Then the DAAS mode of tuning is enabled at the DME, one of these three sources will supply the DME tuning data. The DME channeling switch then enables the desired tuning source. The KN 62A tuning format is the 2 by 5 code. Approximately three seconds are required to tune the KN 62A and acquire valid distance.

To verify the auto tuning function, or to read the DME channel, data is read from the internal tune bus. This data is serial BCD information. A sync and clock are available to strobe this data into the interface.

The following switches are used by the pilot for radio system mode selection:

NAV 1 Manual/DAAS

NAV 2 Manual/DAAS

DME NAV 1/DAAS/NAV 2

ILS Source NAV 2/DAAS/NAV 2

VOR Source NAV 2/NAV 2

Complete pilot backput in a manual mode of operation is assured by the Manual position of the switches.

Range information from the KN 62A is 18 bits of serial BCD data. A synchronous clock is provided to shift the data into the interface for processing. The microprocessor will convert this data

to a 15-bit binary word (LSB = 0.02 NM) and maintain the current distance code in the data block.

2.3 DAAS OPERATIONAL EVALUATION

Pilot evaluation of the DAAS functional configuration has been conducted on the DAAS flight simulator, Figure 2-14. Extensive refinement of the functional configuration has resulted. Following is a description of the simulator evaluation program and the evaluation results.

2.3.1 Summary of Results

A simulator program was conducted with the objective of determining areas where system improvement might be accomplished. Specific system improvement proposals were identified and discussed by the simulator pilot subjects and the DAAS system engineers. Changes were defined based on both their desirability and their effect on DAAS complexity.

System improvements are those changes which would enhance the operational acceptability of the DAAS pilot/system interface. An iterative approach to the simulator program allows the verification of the DAAS functional performance, including improvements as they are defined.

Simulator program change proposals were judged in light of the over-all objectives of DAAS; i.e., improve the safety and dependability of general aviation IFR operations without increasing pilot proficiency requirements or the cost of the avionics.

ORIGINAL PAGE IS OF POOR QUALITY



Figure 2-14. DAAS Simulator

Two General Aviation pilot evaluations were conducted during the development of DAAS prior to this report. In addition, NASA Research Pilot Gordon Hardy examined DAAS frequently during DAAS development.

The first evaluation was conducted in October 1979. Three General Aviation pilots participated. The three pilots were:

J. Lindberg, Instrument Flight Training, a Division of Van Dusen;

R. Albertson, representing King Radio; and W. Unternaehrer,

Honeywell Avionics Engineering. All three have airline type pilot ratings, although they have never flown for an airline.

Two pilots, Lindberg and Albertson, are designated FAA Flight Examiners. Pilot participant experience is described in Section 3.1 of this report.

A four hour system briefing was conducted followed by one hour of simulator time for each evaluation pilot. Following this exposure to the system, a four hour debrief and discussion was conducted on all functions examined in the simulator. Comments were favorable, and a number of DAAS features were considered excellent. For example, the capability of map slewing and automatic waypoint generation received high ratings. The evaluation results were positive for the most part, though some concerns were pointed out. As example of a concern was the effectiveness of touchpoint data entry both on the ground and during flight. The problem centers around inadvertent entries and concern for difficulty making data entries during flight turbulence.

There were thirty-five pilot comments made regarding suggestions for improvements to the DAAS. Many of these have subsequently been incorporated.

The second evaluation was conducted on March 1980. Four General Aviation pilots participated. The four pilots were: D. Rodgers, King Radio; R. Albertson, King Radio; W. Unternaehrer, Honeywell; and Larry Peterson, Honeywell. A detailed briefing was performed. The pilots then flew a scenario (see paragraph 2.3.2, scenario) in the simulator which required input of initial data, navigation data, checklists, interaction with EHSI and autopilot. Man Machine Science specialists monitored each pilot in his performing the scenario. Questions and comments of a human engineering nature were recorded. Following the flights each pilot filled out a questionnaire. The combination of close monitoring during the scenario flight, the questionnaire data, and individual pilot debriefs provided comprehensive evaluation of the DAAS. This information has been assessed and the results are discussed in section 3 of this report.

The evaluation participants were generally enthusiastic about the DAAS concept and functional configuration. Access to data was considered to be significantly enhanced. Navigation, with stored data base and map display, was considered to reduce pilot work-load and improve pilot capability in the terminal area. DAAS capabilities to support good pilot practices in weight and balance computations and take-off performance computation, as well as DAAS precise navigation capability, were judged to potentially improve general aviation flight safety.

Evaluators generally agreed that (1) DAAS type systems can provide greatly expanded functional capabilities, and (2) minimizing complexity and optimizing the pilot system interface is a major challenge.

2.3.2 Simulator Description

- 2.3.2.1 <u>General Purpose Facility</u> -- The DAAS simulator is a general purpose facility consisting of the following primary components:
 - Data General Eclipse S/200 CPU
 - Data General Nova 3/12 CPU
 - 16-bit parallel DMA between above CPUs
 - Datel System 256 Hybrid I/O Unit with 32 D/A and 64 A/D channels
 - Discrete I/O with 16 inputs and 18 outputs
 - Megatek MG552 Graphics Generator Unit
 - Pace 231R Analog Computer

The Nova 3/12 CPU and Megatek graphics unit generate multiplexed alphanumeric and graphic formats with associated blanking signals to drive two independent direct-draw CRT displays. Other digital simulation tasks and hybrid I/O are performed by the Eclipse S/200.

2.3.2.2 <u>DAAS Simulation Hardware</u> -- The fixed base mockup of the pilot's control station includes seat, instrument panel, flight controls, and engine controls configured to the approximate dimensions in a Cessna 402. Since outside visual scene generation was not available, only IFR flight conditions were simulated.

<u>Functional Controls</u> -- The following pilot controls are functional in the simulator:

- Ailerons and Elevator -- Spring centered control wheel with hydraulic dampers on each axis.
- Rudder -- Spring centered pedals.
- Elevator Electric Trim Switch -- On control wheel.
- Flap Position.
- Autopilot Mode Control -- King KMC 340.
- Control Wheel Steering Switch -- On control wheel.
- Autopilot Dump Switch -- On control wheel.
- Go-around Switch -- On left throttle grip.
- Throttle -- Left lever functional.
- RPM -- Left lever functional.
- Mixture -- left lever functional.
- Gear Switch.
- IDCC Touch Panel -- Eight touch points.
- IDCC Function select Keys -- 18 keys.
- IDCC Alphanumeric Keypad -- 15 keys.
- IDCC Enter and Backspace Keys.
- EHSI Cursor Slew Control

<u>Functional Displays</u> -- The following pilot displays are functional:

- FDI -- King KCI 310
- EHSI -- 4 x 5-inch direct draw CRT (Tektronix Mod. 608)
- IDCC -- 4 x 5-inch direct draw CRT (Tektronix Mod. 608)
- RMI -- King KI 581
- Mode Annunciator -- King KAP 315
- Airspeed Indicator -- 2.75-inch meter with 250-deg. pointer range
- Baro Altimeter -- three pointer DC servo drive
- Vertical Speed -- 250-deg, 2.75-inch meter
- Manifold Pressure 250-deg, 2.75-inch meter
- RPM -- 250-deg, 2.75-inch meter
- Fuel Flow -- 250-deg, 2.75-inch meter
- a Aircraft Clock
- Master Caution and Warning Lights

The KI 581 Radio Magnetic Indicator, listed above, is similar in appearance to the KI 226, and was recommended by King Radio for use in the simulator. Simulated IDCC and EHSI displays differ from the 4.5-inch-square displays with in-raster symbol generation presently planned for use in DAAS. The simulator facility is currently limited to direct-draw display generation. Tektronix 608 Monitors approximate the planned for use in DAAS. The simulator facility is currently limited to direct-draw display generation. Tektronix 608 Monitors approximate the planned DAAS display dimensions to within 0.5 inch, and can be driven by the X.

Y, Z, and blanking outputs produced by the facility's existing graphics generator unit.

Installation of one King KY 196 Comm Transceiver and a KT76A Transponder in the simulator is included to provide the means for exercising these functions in the pilot's procedural sequence.

Labeled paste-ups of all remaining indicators are included on the simulated instrument to demonstrate DAAS and backup pilot panel layouts.

Simulator Hardware Interfaces -- Figure 2-15 summarized interfaces between the facility computers and control/display devices. The analog computer is used only for gain and null settings on proportional controls and DC-meter panel instruments.

2.3.2.3 <u>DAAS Simulation Software</u> -- Software was developed for digital simulation of the following system and environmental components:

- Aircraft and engine
- Flight control system
- Mean wind and gusts
- Ground navigation
- Navigation algorithms
- Sensor outputs
- IDCC functions, paging and display formats
- EHSI display formats
- System failures and other unplanned events




Figure 2-15. Simulator Hardware Interfaces

<u>Digital Program Description</u> -- The digital program is divided into a set of modules or subroutines, all sharing a common data base. This data base consists of two arrays: one real array consisting of up to 1000 real variables, and the second an integer array consisting of up to 500 integer or logical variables. Each element of the arrays is equivalenced to a mneumonic of six letters or less. The following software subroutines are included:

ARPLN -- Aircraft equations of motion

LACL -- Lateral axis control law

PACL -- Pitch axis control law

ENGIN -- Engine model

MODSL -- Mode select logic

ADC -- Analog to digital converter

SERVO -- Servo model

DISIO -- Discrete input/output processing

SNMOD -- Sensor model

ALTHLD -- Altitude hold model

NAVCM -- Navigation computations

SERIO -- Serial input/output processing

IDCC - IDCC display processing

EHSI -- EHSI display processing

INSTR -- Instrumentation signal processing

All subroutines are called by an executive routine which also controls system timing by utilizing an interrupt driven real time clock.

2.3.3 Pilot Evaluations

Several indices were used to assess the pilots' responses to the DAAS system simulation. These included observation of the pilots during the actual simulation exercise, as well as a paper-and-pencil questionnaire and informal debriefings following each session. The combination of these evaluation techniques yielded a relatively comprehensive assessment of the pilots' impressions of DAAS. These results are presented in section 4 of this report. In addition to evaluative data, the pilots were also asked to provide general background information. Each pilot was asked to fill out a brief questionnaire outlining his previous flight history and current credentials. Appendix A contains the subject profiles that were compiled from the completed questionnaires.

2.3.4 Evaluation Procedure

The DAAS evaluations consisted of four elements:

- 1. Pilots were briefed on the DAAS system and the aspects of it that were to be evaluated.
- 2. Pilots then flew the simulator following a scenario for a planned flight of approximately 15 to 20 minutes.
- 3. Immediately following the simulator exercise, each pilot filled out a questionnaire while elaborating verbally on their responses.
- 4. Debriefing by means of an informal, on-going discussion with one or more pilots present completed the evaluation procedure.

2.3.4.1 <u>Briefing of Subjects</u> -- Briefings were given to the DAAS evaluation pilots who were not directly associated with the design of DAAS. These briefings emphasized the functional characteristics of DAAS and the particular aspects that were to be evaluated.

The briefings followed the outline as follows:

- 1. Objectives of DAAS
- 2. Description of Controls and Displays
 - 2.1 Airspeed Indicator
 - 2.2 Attitude Director Indicator
 - 2.3 Mode Annunciator Panel
 - 2.4 Altimeter
 - 2.5 Altitude Rate Indicator
 - 2.6 Electronic Horizontal Situation Indicator and Controls
 - 2.7 Engine Instruments
 - 2.8 Integrated Data Control Center
 - 2.8.1 Display
 - 2.8.2 Touchpoints
 - 2.8.3 Page Select Buttons
 - 2.8.4 Navigation Buttons
 - 2.8.5 Keyboard
 - 2.9 Caution and Warning Lights
 - 2.10 Autopilot Control Panel
 - 2.11 Miscellaneous Controls

- 2.11.1 Flap Control
- 2.12.2 Throttle Quadrant
- 2.11.3 Go Around Switch
- 2.11.4 Trim Switch
- 2.11.5 Autopilot Disengage Switch
- 2.11.6 Control Wheel Steering Switch
- 3. IDCC Functions and Pages
 - 3.1 Initialization
 - 3.2 Weight and Balance
 - 3.3 NAVAID Data and Storage
 - 3.4 Waypoint Data
 - 3.5 Flight Status
 - 3.6 Take Off and Cruise Performance
 - 3.7 Check Lists
 - 3.8 Emergency Procedures
- 4. EHSI Functions and Features
 - 4.1 Heading Indication & Heading Select
 - 4.2 Display Format
 - 4.2.1 RNAV linked
 - 4.2.2 RNAV unlinked
 - 4.2.3 VOR
 - 4.2.4 ILS
 - 4.3 Vertical Track Angle and VNAV
 - 4.4 Waypoint Bearing Indicator

4.5 Miscellaneous Indications

MDA or DH

Waypoint in use and available

Course

Distance to Waypoint

Time to Waypoint

Waypoint Altitude

Radios in use

- 4.6 Heading/North Up
- 4.7 Map Scales

5. Navigation Features

- 5.1 Map Review
- 5.2 Map Slew
- 5.3 Map Return
- 5.4 Use Button
- 5.5 Course Select
- 5.6 Auto Sequence
- 5.7 Horizontal Direct To
- 5.8 VNAV
- 5.9 Waypoint Generate
- 5.10 Delete Waypoint
- 5.11 Insert Waypoint
- 5.12 Cursor Use

- 6 Attitude Director Indicator
 - 6.1 Horizon
 - 6.2 Command Bars
 - 6.3 Localizer Deviation
 - 6.4 Glide Slope Deviation
 - 6.5 VNAV Deviation
 - 6.6 MDA and DH Indicators
- 7. Autopilot Mode Select Panel
 - 7.1 Yaw Damper
 - 7.2 Flight Director
 - 7.3 Autopilot
 - 7.4 Altitude Arm, Hold and Trim
 - 7.5 VNAV
 - 7.6 Heading Select
 - 7.7 Approach
 - 7.8 Navigation
- 2.3.4.2 Evaluation Scenario, Minneapolis Area -- The evaluation scenario was planned for approximately 15 to 20 minutes of flight starting with a takeoff from the Minneapolis, St. Paul International Airport as waypoint 1; hence to waypoint 2, STILS intersection; hence to waypoint 3, RENEW intersection; hence to waypoint 4, BONNA Initial Approach Fix for an RNAV approach to Rwy 29 Right, with waypoint 5 the missed approach point located at the landing end of Rwy 29 Right. Figure 2-16, Minneapolis local area victor airway IFR map, describes the flight route.




Figure 2-16. Evaluation Scenario Chart (Minneapolis Local Victor Airway Chart)

The flight time of 15 to 20 minutes was of sufficient duration to permit the exercising of the DAAS functions. Preparation for the flight, the entry of data via keyboard into the IDCC such as take-off performance calculations, weight and balance etc., took an additional 15 to 20 minutes. Thus, the evaluation pilot was in the simulator seat for about 40 minutes, which was not long enough for either fatigue or boredom to enter the evaluation equation.

The NAVAID Data entered into DAAS is described in Table 2-1 and consists of the VOR/DME stations used for waypoint definition. Table 2-2 lists the waypoints and describes the vertical navigation profile. Figure 2-17 is the RNAV approach chart for Minneapolis, St. Paul, International Airport Rwy 29 Right.

The following is a description of the scenario in the order of actual events:

- 1. Review flight plan as shown in Figure 2-16.
- 2. Power-up system IDCC INIT PAGE appears. Pilot enters zulu time (GMT).
- 3. Press MENU button and select touchpoint WEIGHT & BALANCE
- 4. WEIGHT & BALANCE. Pages 2 through 3 Enter passenger, cargo and fuel weight as appropriate. Review results on page 3 to see that the calculated CG is between the forward and aft limits and that the maximum takeoff weight is not exceeded. Transfer results to INIT page.
- 5. Press MENU button and select touchpoint TAKEOFF PERFORMANCE.

ORIGINAL PAGE IS OF POOR QUALITY

Table 2-1. NAVAID Data for Evaluation Scenario

NAVAID No.	Frequency I.D.	Elevation	Latitude	Longitude	Variation •	
1	MSP 117.3	880	N4508.7	W09322.4	6E	
2	FGT 115.7	930	N4437.9	W09310.9	6E	
3			N	w		
4			N	W		
5			N	w		
6			N	W		
7			N	W		
8			N	W		
9 .			N	W		
0			N	W		

ORIGINAL PACE FOOF POOR QUALITY

Table 2-2. Waypoint Data for Evaluation Scenario

				DAZ	AS Wayp	oint Data	Sheet				
WΡ	NAVAID No. ID	Frequency	Elevation (Ft)	CRS1 (Deg)	CRS2 (Deg)	Radial (Deg)	Distance (NM)	Altitude (Ft)	Offset (NM)	RNAV/VOR/ILS	MDA
1	1 MSP					151,0	17.1				
2	1 MSP					094	28.0	3000	4.0	:	
3	1 MSP		Initial Ap	proach	Fix	110	32.0	4000	2.0		
4	2 FGT ◀	>	IA	. <u>r</u>	<u> </u>	035	13.0	4000			
5	2 FGT				}	352	15.0	1400	1.6		1400
6	5	·		,			MDA	\supset			
7	~	Missed App (MA	roach Point				MDA) I			
8			í	1	<u> </u>]	i		
9					!				}	i	
0	<u> </u>						ŀ	1	!	1	1




Figure 2-17. Minneapolis-St. Paul International RNAV Rwy 29 Right

- 6. TAKEOFF PERFORMANCE Enter all appropriate data for takeoff. Review results of computation on page 2.
- 7. Press MENU button and select touchpoint CRUISE PERFORMANCE
- 8. CRUISE PERFORMANCE Enter appropriate data for cruise.
- 9. Press NAVAID DATA button enter VOR/DME data for appropriate NAVAID stations required to define waypoints for flight planned. See Table 2-1 for NAVAID data entry. Press NAVAID SUM button to review the data entered.
- Press WAYPOINT DATA button enter waypoints that define intended flight. Review data entered by flipping through waypoint pages 1 through 5. See Table 2-2 for waypoint (WP) data for evaluation scenario.
- 11. Using Electropic Map Slew lever and appropriate map scales, review the entire flight.
- 12. Prepare for takeoff using IDCC checklists.
- 13. Takeoff; engage auto pilot after airborne; climb to 400 feet; use heading select to turn for an intercept with course 1 of WP2; activate autopilot NAV ARM; and as aircraft couples and settles down on course 1, select autopilot VNAV. Press AUTO SEQ button for course 1 to switch automatically to course 2.
- 14. Halfway to WP3, make WP3 active and press USE button.
- 15. Press FLIGHT STATUS button for true airspeed, ground speed, wind, ETA, and fuel available.

- 16. Halfway to WP4, make WP4 active and press USE button.
- 17. Waypoint 4 is BONNA, the initial approach fix (IAF) for approach to Rwy 29 Right. At 3 miles from WP4, slow air-craft to 120 kts and review landing checklist. See Figure 2-17, RNAV Approach Chart Minneapolis Rwy 29 Right.
- 18. Over WP4, extend landing gear and flaps.
- 19. Select WP5 MAP active and press USE button.
- 20. Monitor indicated airspeed to 100 kt and glide slope to about 3 degrees on the EHSI Vertical Track Angle indicator.
- 21. At the minimum descent altitude (MDA) the aircraft goes to altitude hold and passes over WP5 MAP. End of evaluation scenario.
- 2.3.4.3 <u>Post-Scenario Questionnaire</u> -- A post-scenario question-naire was developed to provide <u>quantitative</u> assessment of pilot response to the human factors characteristics of the DAAS simulation scenario exercise. Rating scales were used to assess responses to overall system operation, as well as specific characteristics of the IDCC and EHSI keyboards and displays. The questionnaire addressed each of the following areas:
 - Overall System Operation
 - Workload assessment
 - Adequacy of information provided
 - Relevancy of information provided
 - Time assessment
 - Potential training require the s

- Time
- Method (simulator versus isolates CRT displays)
- IDCC Keyboard and Display
 - Ease of data entry
 - Time required
 - Keyboard location
 - Keyboard format
 - Adequacy of information displayed
 - Major functions/menu selections
 - Feedback for error corrections
- EHSI Keyboard and Display
 - Ease of data entry
 - Waypoint insertion
 - Keyboard location
 - Adequacy of information displayed
- General Comments

The post-scenario questionnaire was given to each pilot immediately following the simulation exercise. Administration of the questionnaire was informal, and verbal comments from the pilot elaborating on their responses to each item were encouraged. Thus, the questionnaire also served as a point of departure for the debriefing discussions which followed.

2.3.4.4 <u>Debriefing</u> -- Debriefing involved informal ongoing discussion with one or more of the pilots present at any given time. Thus, pilots were able to discuss the simulation from several

viewpoints. The result was an indepth analysis of both the functional characteristics of DAAS and its general acceptability as a future on-board system.

2.4 FAILURE MODE AND EFFECTS ANALYSIS (FMEA)

The intention of this FMEA is to analyze the effects of failed DAAS elements, the probability of the failures, and how the pilot workload and the flight safety situation are affected by the failures. The importance of the safety pilot is discussed. DAAS compatibility to FAR Parts 23 and 91 is also assessed.

Assessment of DAAS compliance with FAR requirements, and analysis of failure effects in general can be summarized as follows:

• Failure Effects with Respect to FAR Requirements

- Of the 86 DAAS elements analyzed, FAR Parts 23 and 91 VFR and IFR CAT 1 requirements are applicable to 36. There are no conflicts for fault-free DAAS.
- 25 DAAS elements may fail without violating any FAR requirements.
- 11 failed elements violate FAR 23.1329.e for the initial DAAS design. These 11 failures violate FAR 23.1329e which says:

"Each system must be designed so that a single malfunction will not produce a hardover signal in more than one control axis." Recommendation -- The FAR 23.1329.e conflict was resolved by introducing 3 hardware limiters located down stream of the pitch, roll, and yaw D/A converters. These limiters will prohibit any DAAS computer failure from commanding the servos hardover.

- <u>Failure Effects</u>, <u>General</u> -- The 86 DAAS elements were split into the 4 failure categories:
 - 22 Elements Category 1, Failure Effects Negligible
 - 36 Elements Category 2, Failure Effects Inconvenient
 - 26 Elements Category 3, Failure Effects Demanding
 - 2 Elements Category 4, Failure Effects Critical

The two critical failures are Aircraft 28-Vdc and Avionics 28-Vdc bus. The category 4 failure probability is very low, less than 10^{-6} for a 4-hour flight.

Recommendations

- 1. The DAAS failure effects are not critical with the exception of the Aircraft and Avionics 28-Vdc bus failure. The probability of these failures happening is low enough to make them negligible. No action required.
- 2. Flight safety is dependent on the safety copilot. He should closely monitor the DAAS performance, especially at low altitude, take-off, and landing conditions.

Following are the details of the analysis including description of the DAAS system analyzed, assessment of DAAS compliance with FAR requirements, and description of the FMEA results.

2.4.1 DAAS System Description

The present DAAS is defined in the following documents:

- 1. Functional description, NASA DAAS Phase 2, dated October 15, 1980.
- 2. DAAS System Specification (YG1210) preliminary copy December 1979.
- 3. Software requirements for the DAAS FCS, Version 5, October 1979.
- 4. Miscellaneous diagrams and papers describing the Cessna 402B cockpit, servos, etc.

2.4.2 Assessment of Compliance With FAR Requirements

FAR Parts 23 and 91 are applicable to DAAS. The applicable FAR paragraphs are restated below and comments given as to how they are net by DAAS.

2.4.2.1 <u>FAR Part 23 Equipment, Systems and Installations</u> -- The DAAS, when installed in the aircraft, must meet the following restated FAR Part 23 requirement:

Requirement, 23.1309

- (a) Each item of equipment, when performing its intended function, may not adversely affect:
 - (1) The response, operation, or accuracy of any equipment essential to safe operation; or
 - (2) The response, operation, or accuracy of any other equipment unless there is a means to inform the pilot of the effect.
- (b) The equipment, systems, and installations of a multiengine airplane must be designed to prevent hazards to the airplane in the event of a probable malfunction or failure.
- (c) The equipment, systems, and installations of a single-engine airplane must be designed to minimize hazards to the airplane in the event of a probable malfunction or failure.

Comment:

The DAAS development program should eliminate adverse affects specified in item a. Tests in simulators, qualifications tests, and checkout in the aircraft shall verify that no undesired interaction exists.

The DAAS design and included limiters, monitors, warnings, etc., satisfy the item b or c requirements.

2.4.2.2 <u>FAR Part 23</u>, <u>Requirements of the Autopilot</u> -- The Autopilot (sensors, computer, servos) must meet the FAR Part 23.1329 requirement as follows:

Requirement, 23.1329 a to g

- (a) Each system must be designed so that the automatic pilot can;
 - (1) Be quickly and positively disengaged by the pilots to prevent it from interfering with their control of the airplane; or
 - (2) Be sufficiently overpowered by one pilot to let him control the airplane.
- b, c, g requires a certain cockpit design in order to eliminate pilot confusion and simplify use of the autopilot.
- a,d,e,f requires a certain system design to minimize the impact of autopilot malfunction.

Comment:

The autopilot dump switches (control wheel, N_Z -accelerometer) and the slip clutch included in the elevator, aileron, and rudder servos provide the required protection.

The slip clutches are designed to prevent excessive accelerations.

Requirement 23.1329 b

(b) Unless there is automatic synchronization, each system must have a means to readily indicate to the pilot the alignment of the actuating device in relation to the control system it operates.

Comment:

The position of the control wheel, pedals and the trim indicators indicate the alignment.

Requirement 23.1329 c

(c) Each manually operated control for the system operation must be readily accessible to the pilot. Each control must operate in the same plane and sense of motion as specified in 23.779 for cockpit controls. The direction of motion must be plainly indicated on or near each control.

Comment:

DAAS panel layout agrees with the FAR requirements.

Requirement 23.1329 d

(d) Each system must be designed and adjusted so that, within the range of adjustment available to the pilot, it cannot produce hazardous loads on the airplane or create hazardous deviations in the flight path, under any flight condition appropriate to its use, either during normal operation or in the event of a malfunction, assuming that corrective action begins within a reasonable period of time.

Comment:

Met by

- 1. Software limiters, 3-axis
- 2. Software "faders" in pitch and roll

- 3. Slip clutches
- 4. Pitch trim monitor
- 5. The Nz> "1G-Dump accelerometer".

Requirement 23.1329 e

(e) Each system must be designed so that a single malfunction will not produce a hardover signal in more than one control axis. If the automatic pilot integrates signals from auxiliary controls or furnished signals for operation of other equipment, positive interlocks and sequencing of engagement to prevent improper operation are required.

Comment:

This requirement can be met by implementation of hardware servo command limiters. (Note: Limiters have been added to flight system.)

Requirement 23.1329 f

(f) There must be protection against adverse interaction of integrated components, resulting from a malfunction.

Comment:

Met by

- 1 . Buffers eliminating part damage.
- 2. Limiters and monitors eliminating excessive commands.

Requirement 23.1329 g

(g) If the automatic pilot system can be coupled to airborne navigation equipment, means must be provided to indicate to the flight crew the current mode of operation. Selector switch position is not acceptable as a means of indication.

Comment:

The annunciator panel provides the requested information.

- 2.4.2.3 <u>FAR Part 91</u>, <u>Instruments</u>, and <u>Equipment Requirements</u> -- FAR Part 91.33, a to e, specifies instrument and equipment required for powered civil aircraft with U.S. air worthiness certificates as follows:
- 91.33 (a) General
 - (b) VFR flight, day
 - (c) VFR flight, night
 - (d) IFR flight, category I
 - (e) IFR flight, category above 24,000 feet
 - (f) IFR flight, category II

IFR category II is not applicable to DAAS.

The requirements are summarized as follows.

Requirement 91.33b

- (b) Instruments required for VFR Flying, Day
 - (1) Airspeed indicator.

- (2) Altimeter.
- (3) Magnetic direction indicator.
- (4) Tachometer for each engine.
- (5) Oil pressure gauge for each engine using pressure system.
- (6) Temperature gauge for each liquid-cooled engine.
- (7) Oil temperature gauge for each air-cooled engine.
- (8) Manifold pressure gauge for each engine.
- (9) Fuel gauge indicating the quantity of fuel in each tank.
- (10) Landing gear position indicator, if the aircraft has a retractable landing gear.

<u>Comment</u> -- The DAAS instrumentation includes the basic instruments required for VFR flight during daytime.

Requirement 91.33c

(c) For VFR night flights additional lights and an anticollision light system are required.

<u>Comment</u> -- It is assumed that the DAAS aircraft is properly equipped in this respect.

Requirement 91.33d

(d) For IFR flight the following instruments and equipment are required:

- (1) Instruments and equipment specified in paragraph (b) of this section and for night flight, instruments and equipment specified in paragraph (c) of this section.
- (2) Two-way radio communications system and navigational equipment appropriate to the ground facilities to be used.
- (3) Gyroscopic rate-or-turn indicator.
- (4) Slip-skid indicator.
- (5) Sensitive altimeter adjustable for barometric pressure.
- (6) A c ock displaying hours, minutes, and seconds with a sweep-second pointer or digital presentation.
- (7) Generator of adequate capabity.
- (8) Gyroscopic bank and pitch indicator (artificial horizon).
- (9) Gyroscopic direction indicator (directional gyro or equivalent).

Comment -- The above listed instrumentation are included in DAAS.

There is no requirement on redundancy stated in this paragraph.

Requirement 91.33e

(e) IFR flight at and above 24,000 feet MSL.

If VOR navigational equipment is required under paragraph

(d) (2) of this section, no person may operate a U.S. registered civil aircraft within the 50 states, and the District of Columbia, at or above 24,000 feet MSL unless that aircraft is equipped with approved distance measuring equipment

(DME). When DME required by this paragraph fails at and above 24,000 feet MSL, the pilot in command of the aircraft shall notify ATC immediately, and may then continue operations at and above 24,000 feet MSL to the next airport of intended landing at which repairs or replacement of the equipment can be made.

2.4.3 DAAS Failure Modes and Effects Analysis Results

The DAAS FMEA was conducted to determine effects of failures in the DAAS hardware. Assumptions for the analysis were as follows:

- DAAS is designed for category I IFR operation
- All single failures and dual failures with high failure rates are studied.
- Any failure in any element is assumed to result in a lost function of that element, which makes this a "worst case" analysis.
- \bullet The autopilot slip-clutches, the pilot (and $N_{\rm Z})$ dump switches, and the pilot and copilot override possibilities provide the pilots adequate means to safely handle any single control axis hardover servo failure.
- The probability of a critical situation less than 10^{-6} in a 4-hour flight is judged to be negligible.
- Preflight test and inflight bit are performed. Autopilot dump switching, normal acceleration dump switch, and servo clutch switches must be checked.

The preflight test coverage will be less than 100 percent due to nontestable elements. Expected fault detection coverage is:

Sensors			70-80%
Computers			90-95%
Indicators and	Servos		80-90%
Monitors, Dump	Switches,	Clutches	100%

Some takeoffs may take place with faulty system elements due to less than 100 percent preflight test coverage.

- Effective DAAS software validation will be performed.
- The four Failure Categories are:
 - 1. Negligible to the pilot
 - 2. Inconvenient to the pilot
 - 3. Demanding to the pilot
 - 4. Critical, evident risk for catastrophe

Fault categorization assumes a single pilot. In the conclusions, judgments are given on how the safety pilot improves the DAAS flight-safety situation and how failure probabilities affects the DAAS flight safety situation.

- FAR Part 23 and 91 requirements are assumed to define a minimum avionics system, which is normally safe to fly.
- DAAS failure rates used in the FMEA are as listed in Table 2-3. The failure rate is the probability of a failure in a DAAS element during 1 hour flight.

ORIGINAL PAGE IS OF POOR QUALITY

Table 2-3. DAAS Flements Failure Rates

Elements	lyre No.	Quantity n	Failure Rates	Total Rates	Comments		
1. DAAS Elements Harawired to DAAS-Computers							
Bubble Memory		1	500	500	1		
CPU & RAM/PROM	8086	7	60	420	(20 and 80%)		
Radio Adapt. Box	(8748)	1	40	40			
BIM	(9914)	8	12	96			
488-Bus		1.	1	1	Incl. 2 Connectors		
A/D, D/A, Mux		1	60	60			
EHSI		1	300	300	,		
IDCC		1	300	300			
IDCC Keyboard		1	50	50			
ADI	EC1310	1	340	340			
RMI	KZ226	1	330	330			
CX-Sens. & Indic.		1	100	100			
Pitot System L		1	50	50	Not electrically hardwired!		
Encod. Altim.	-571	1	200	200			
Audio Cont. Panel	KMA 24	1	200	200			
Comm. Tranceivers	KY196	2	330	660			
VOR Receivers	KN53	2	250	500			
DME Receivers	KN62A	1	500	500			
Transponder	KT76A	1	400	400			
Mode Controller	KMC340	1	340	340			
Annunciator Panel	KAP315	1	30	30			
MAG X MTR	KMT112	1.	20	20			
Directional Gyro	KSG105	1	330	330			
Slave Control	KA-51A	1	10	10	•		
Vertical GYRO	VG 208	1	330	330			
Radar Altimeter	RT-271	1	500	500			
ADC	KDC-380	1	200	200			
True Air Speed	VA 210	1	100	100	Incl. F/V Converter		
Outer Air Temp.		1	10	10	Incl. Sign. Conditioning		
Yaw Rate GYRO	GG 2472	1	50	50			
Engine Map	ļ	2	5	10			
Engine RPM		2	10	20	Incl. F/V Converter		
Engine Fuel Flow		2	5	10	,		
Cowl Flap Pos.		2	5	10			
Flap Pos.	į	1	20	20			
Elev. Trim Pos. ,		1	20	20			
Yaw Servo		1	70	70	Incl. Clutch & Amplif.		

ORIGINAL PAGE IS OF POOR QUALITY

Table 2-3. DAAS Elements Failure Rates (2 of 2)

	Type No.	Quantity n	Failure Rates	Total Rates	Comments			
Roll Servo		1	70	70	Incl. Clutch & Amplif.			
Pitch Servo	}	1	70	70	Incl. Clutch & Amplif,			
Pitch Trim Servo		1	50	50	Incl. Clutch & Amplif.			
2. DAAS Instrumentation not Hardwired to DAAS Computers								
IAS	1	1	280	280	Pitot System L.			
VSI	1	1	100	100	Pitot System L.			
Turn & Bank	1	1	150	150	· -			
Fuel Quantity	1	1	150	150				
Map		1	10	10				
RPM	1	1	10	10				
Fuel Flow		1	10	10				
EGT	ĺ	1	10	10				
Engine Status		2	20	40				
I 3. <u>Co-Pilot Back Up</u>	Instrumen	tation	,	İ	İ			
Pitot System R	1	1 1	50	50	}			
IAS		1	280	280				
Altimeter		1	180	180				
VSI		1	100	100				
Turn & Bank		1	150	150				
Artific. Horizon	KG258	1	670	670	•			
PNI	KC525A	1	330	330				
Slave CTRL	KA-51A	1	10	20				
Direct. GYRO	KG102-A	1	400	400				
MAG X MTR	KMT112A	1	20	20	,			
Comm. Tranceiver	422A	1	660	660				
VOR/GS, Receiver	442A/443A	1	500	500	Incl. Nav. Converter			
4. Electrical Power	System	ţ	ļ	İ				
A/C 28VDC Bus		1	<.1	<.1	Redundant Alternators			
Avionics 28VDC Bus		1	<.1	<.1	<pre>pilot disconnect faulty battery!!</pre>			
DAAS A 28VDC Bus		1	~.1	~.1				
DAAS B 28VDC Bus		1	~.1	~.1	Valid as long as DAAS Battery Lasts (~1 hr.)			
DAAS Battery Chrgr		1	5	5	, , , , , , , , , , , , , , , , , , , ,			
DAAS Battery		ı]	100	100				
DC/AC Invertor		1	10	10				
DE/DC Converter		2	15	30	·			

For the failure probability estimates, 4 hours flight time are assumed.

The failure rates in Table 2-3 are collected from adjusted MIL-HDB-217B data, vendors reliability data, Honeywell predicted failure rates and by comparison to known similarly complex elements.

Ine failure rates should be representative of components and parts available in 1979/80.

FMEA results are compiled in Appendix B. The DAAS elements are defined on these forms and the type of failure and the failure-rates are also listed. The impact of a faulty element on downstream DAAS elements is also indicated.

Finally, a judgment is made as to how the failed element will increase the pilot effort required to complete his flight. The failures are divided into the four categories on the basis of this judgment.

The DAAS failure category is assigned assuming a co-ilot in the right seat.

Appendix B also indicates whether:

- FAR requirement are applicable and met.
- Failure probabilities are significant to the risk situation,
- DAAS would be safe to fly with the analyzed element faulty.

The FMEA covers the consequences of 86 failed DAAS elements.

Table 2-4 summarizes failure categories and indicates whether applicable FAR requirements are met. Comments on redundancy, failure probability, etc., are given for some failed elements.

These FMEA results indicate that fault-free DAAS meets the FAR Part 23 and 91 requirements. DAAS does provide the required means for override and disengage after a failure.

FAR requirements may more or less be violated if DAAS elements fail. Of the 86 failed DAAS elements studied, FAR VFR or IFR Cat I requirements apply to 36. For these 36 failed elements, 11 violate the FAR requirements. FAR requirements that apply to general VFR flight, and 6 of these are not met. 13 requirements applying to IFR Cat I, 5 are not met. 16 requirements apply to IFR Cat II; DAAS is not certified for Category II.

The violated paragraph is 23.1329(e) which says:

"Each system must be designed so that a single malfunction will not produce a hardover signal in more than one control axis."

Violation occurs for failures in:

- A/P, NAV, Bus Controller, Processors
- 488-Bus

Table 2-4. Summary of the DAAS Failure Modes and Effects Analysis

Failure No.	Element	Far Req.	Failure Category	Comments
1	Encod. Altimeter	OK Cat 1	3	Misleads ATC Proximity W-Error
2	Altimeter Co-Pilot	OK Cat 2	2	proximity "-H1101
3	Radar Altimeter	OK	2	·
4	TAS	N/A	2	ł
5	TAS Pilot	OK Cat 1	2	
6	IAS Co-Pilot	OK Cat 2	1	
7	ADC (380)	N/A	2	Min. Alt. for ALTH Recommended
8	Pitot System L	OK Cat 1	3	
9	Pitot System R	OK Cat 2	1	
10	Oat	N/A	2	
11	Pilot Mag. XTMR	OK Cat 1	3	
12	Pilot Slave Indic.	N/A	1	
13	Pilot Direct GYRO	OK Cat 1	3	
14	Pilot RMI	OK Cat 1	2	
15	Co-Pilot Mag. XTMR	OK Cat 2	1	
16	Co-Pilot Slave Indic	N/A	1	
17	Co-Pilot Direct GYRO	OK Cat 2	1	
18	Co-Pilot PNI	OK Cat 2	1	
18	Pilot Turn & Slip	OK Cat 2	1	
20	Co-Pilot Turn & Slip	OK Cat 2	1	1
21	Yaw Rate GYRO	N/A	2	
22	X-Sensor & Indicator	N/A	2	
23	Pilot Vertical-GYRO	OK Cat 1	2	
24	Pilot ADI	OK Cat 1	2	
25	Co-Pilot Artif. Horiz.	OK Cat 2	1	
26	Map Instrument	OK Cat 2	2	
27	RPM Instrument	OK Cat 2	2	
28	EGT Instrument	N/A	2	
29	Eng. Status 1	OK Cat 2	3	Pilot Action
30	Eng. Status 2	OK Cat 2	3	As if Engine Failure
31	Fuel Flow Sens. 1	N/A	2	
32	Fuel Flow Sens. 2	N/A	2	

Table 2-4. Summary of the DAAS Failure Modes and Effects Analysis (Sheet 2 of 3)

Failure No.	Element	Far Req. Met	Failure Category	Comments .
33	Fuel Quantity	OK Cat 2	2	
34	DAAS Map Sensor	N/A	1	
35	DAAS RPM Sensor	N/A	1	
36	Wing Flp. Pos. Sens.	N/A	1	
37	Elev. Trim Pos. Sens.	OK	1	Redundant info. available
38	Cowl Flps. Pos. Sens.	N/A	1	
39	LDG Gear Pos. Sens.	N/A	1	-
40	Door Pos. Sens.	N/A	1	
41	Aux. Fuel Pump Sw.	N/A	1	
42	Cws-Switch & Logic	ок	3	A Software Controlled CWS Light Recommended
43	Go-Around Switch	N/A	3	one Eight Necellandiaea
44	Pitch Trim Switch	N/A	2	
45	Pitch Trim Button	N/A	3	Runaway Not Monitored
46	A/P Dump Sw. & Relay	ОК	3	2 Failures Probab. ~10 ⁻⁷
47 a	Co-Pilot Comm. Transievers, Antennas	OK	1	Duplex Probab. ~ζ·10 ⁻⁶
ъ	Co-Pilot Comm. Transievers, Antennas	ОК	1	
48 a	Pilot Nav. Receiver + Antennas	OK Cat 2	2	
ъ	Co-Pilot Nav. Receiver + Antennas	OK Cat 2	1	
49	DME Receiv. + Ant.	OK Cat 2	2	Single DME
50	Transponder + Ant	N/A	1	No Outsignal ATC Problem!
51	Audio Headsets	OK	2	DAAS Duplex
52	Switch Nav 1 Sel.	N/A	2	
53	Switch Nav 2 Sel.	N/A	2	
54	Switch DME Sel.	N/A	2	
55	Switch VOR Sel.	N/A	1	
56	Switch Loc/GS Sel.	N/A	2	
57	IDCC Keyboard	N/A	3	Missed Pilot Input Check. Low Probability
58	IDCC Selector Switch	N/A	2	
59 ·	IDCC CPU, Display	N/A	2	
60	EHSI Selector Switch	N/A	2	7720

Table 2-4. Summary of the DAAS Failure Modes and Effects Analysis (Sheet 3 of 3)

Failure No.	Element	Far Req. Met	Failure Category	Comments
61	EHSI CPU, Display	N/A	2	
62	Annunciator Panel	OK	2	
63	Mode Cont. Trim/Hdg.	OK	2	
64	Mode Cont, Toggle Sw.	OK	2	
65	Mode Cont. Solen. Sw.	OK	2	
66	A/P Yaw Clutch, Servo	OK	2	
67	A/P Roll Clutch Servo	OK	3	· .
. 68	A/P Pitch Clut. Servo	OK	3	
69	A/P Pitch Trím Servo	ок	3	
70	Clutches Common Logic	OK	3	
71	A/P-I/O CPU, BIM A/P-I/O A/D, D/A, MUX	NOT OK	3	Fault During Critical Fault Phases
72	NAV/FLT PLN CPU, BIM	NOT OK	2	Probab. No Recon. 30·10 ⁻⁵ Probab. Recon. 6·10 ⁻⁵
73	Spare CPU, BIM	N/A	2	Probab. <10 ⁻⁶
74	Radio Adapter Box and BIM	N/A	3	Critical Fault Phase
75	Dabs Transponder CPU + BIM	N/A	1	ATC Problem
76	BUS. Controller CPU, BIM	NOT OK	3	Uncertain Warn.
77	488 Bus	NOT OK	3	Critical Fault Phase
78	Bubble Memory	NOT OK	3	Probab. <10 ⁻⁶
79	Cassette	NOT OK	3	Efficient Bite Probab. <<10 ⁻⁶
80	A/C Main 28 VDC Bus	OK 1)	4	Probab. <10 ⁻⁷
81	Avionics 28VDC Bus	OK	4	Probab. <10 ⁻⁷
82	DAAS A-B 28VDC Bus.	NOT OK	3	Probab. <10 ⁻⁷
83	DAAS AC Buses	NOT OK	3	Probab. ~10 ⁻⁵
84	DAAS 15V DC Bus	NOT OK	3	Probab. ~10 ⁻⁵
85	DAAS 12 DC Bus	NOT OK	3	Probab. <<10 ⁻⁶
86	DAAS 5 DC Bus	NOT OK	3	Probab. ~10 ⁻⁵

CESSNA 402B electrical power system with DAAS installed assumed to meet applicable Far requirements.

- Bubble Memory and Cassette
- The Electrical Power Buses

The 23.1329(e) conflict was resolved by introducing three hard-ware limiters located immediately downstream of the pitch, roll and yaw A/D converters in the DAAS hardware. These limiters prohibit any kind of DAAS computer failure from commanding servo hardover. The limiters reduce any DAAS computer hardover failures to:

- Pitch 60% Full Scale
- Roll 30% Full Scale
- Yaw 45% Full Scale

Appendix B contains the complete Failure Modes and effects analyses. Eighty-six failures were defined and categorized as follows.

- Category 1 Failures are negligible to the DAAS pilot; e.g., copilot instruments, door switches, etc.
- Category 2 Failures that cause inconvenience to the DAAS pilot; e.g., loss of ADC-380 RMI, a -Sensor, Annunciator Panel.
- Category 3 Failures during busy or critical flight-phases which can be demanding to the DAAS pilot; e.g., IDCC key-board, engine/status instrument, servos, autopilot dump switch, autopilot processor, bus, and electric power.

ORIGINAL PAGE IS OF POOR QUALITY

Category 4 - Failures that may create a critical situation. The two DAAS Category 4 failures a e loss of the Aircraft and Avionics 28-Vdc Bus. The probability of occurrence is very remote.

Table 2-5 summarizes the number of failures that fall within these failure categories.

Table 2-5. Failure Categorization of the DAAS Elements

	Fail	ure Ca	ategory	7
	1	2	3	4
Number of DAAS Elements	22	36	26	2

The DAAS Category 4 failures have a very low probability of 10^{-6} . They are negligible.

Autopilot Processor failures are demanding during especially low altitude flight phases. The probability of such a failure may be 10^{-5} for a 4-hour flight. It is vital to the DAAS flight safety that the copilot closely monitors the DAAS performance during such conditions.

The DAAS FMEA concludes that, with servo command limiters implemented as recommended, DAAS flight safety is adequate for the demonstration system.

The DAAS system meets the objectives of the program as well as the necessary safety requirements. The conclusions and recommendations pertaining to the DAAS system are presented in Section 4 report. The DAAS design and analysis served as a baseline for the Projected Advanced Avionics System (PAAS), which is discussed in the following section.

SECTION 3 PROJECTED ADVANCED AVIONICS SYSTEM (PAAS)

PAAS is a projected operational version of DAAS. It extrapolates the DAAS concept of fault tolerant integrated avionics to a system that could be produced in the mid-1980s. PAAS is designed to have super functional reliability. The Autopilot/Navigation mean time between loss of function is on the order of 10,000 hours. PAAS can thus provide the dependable pilot relief that is essential for effective flight management by using the expanded functional capabilities provided.

Following is a description of PAAS and an analysis of its reliability, cost, maintainability, and modularity.

3.1 PAAS SYSTEM DESCRIPTION

The PAAS system, Figure 3-1, extrapolates the DAAS concept to a mid-1980s projected operational avionics configuration. PAAS architecture is similar to DAAS; i.e., it is a reconfigurable multiprocessor configuration. PAAS extends the DAAS spare processor redundancy concept to cover all essential avionics processors. PAAS employs a fault tolerant sensor configuration, dual redundant data busses, and dual autopilot servos. Redundancy in sensors, data bus, and servos -- in addition to fault tolerant processing -- is required to cause significant impact to the avionics functional reliability.

PAAS is designed as a minimum cost system that will allow continued operation of essential avionics functions after any single




Figure 3-1. PAAS System Architecture

failure. Functional reliability of navigation and autopilot are emphasized. The PAAS design provides approximately 10,000 flight hours of operation between loss of these functions, as compared to 200 hours for current systems. PAAS includes extensive builtin test for high confidence fault detection (and annunciation) and fault isolation for efficient maintenance.

Following is a description of the PAAS fault tolerant implementation of sensors, data bus, computer, displays, servos, power supplies, and the redundancy management techniques envisioned for the system.

3.1.1 PAAS Sensor Configuration

PAAS sensors required for navigation and autopilot functions are redundant for fault tolerance. Four skewed laser gyros, and four skewed accelerometers are proposed for the projected strap-down attitude heading reference system (AHRS). Dual static and differential pressure transducers are proposed for air data sensing. Dual VOR receivers and single DME are included for NAV inputs. Fuel sensors, engine sensors and configuration monitoring sensors are nonredundant.

Following are details on the unique PAAS ARRS and air data sensor mechanization.

3.1.1.1 <u>PAAS AHRS Mechanization</u> -- The AHRS employs strap-down skewed laser gyros and skewed accelerometers for fault tolerant attitude and rate sensing.

The laser gyro is a solid-state, precision angular rate sensor with a direct digital output. The laser gyro is ideally suited

for strap-down system configurations because it eliminates the need for gimbals, torque motors or other rotating parts. Instead of the rotating mass of a conventional mechanical gyro, the ring laser gyro utilizes two beams of laser light counter-rotating in a closed path. Laser gyro based inertial navigation and inertial reference systems are inherently more reliable and easy to maintain, and they provide the additional benefits of instant on, insensitivity to acceleration error sources, and low life cycle cost.

Four gyros and four accelerometers are employed in a skewed configuration, as shown in Figure 3-2.

Aircraft body rates (and accelerations) are derived from the sensor tetrad as indicated. The three body axis rate components (and accelerations) can be computed from the sensor signals even if one sensor has failed. Fault tolerance is thus provided for the three body rates (and accelerations) with only one added sensor.

A faulty sensor can be detected with high confidence by sensor comparison monitoring, and the fault can be isolated to one sensor either automatically, or by pilot selection should the automatic selection fail as described in paragraph 3.1.7.

The sensed aircraft rate and acceleration signals are converted to digital form in each of the PAAS dual I/O terminals and transmitted to the PAAS AHRS processor for attitude/heading computations. A flux gate signal is also input for long term heading reference. The attitude heading signals are used on the electronic attitude indicator in the PAAS autopilot and navigation functions.

C-2

ORIGINAL PAGE IS OF POOR QUALITY P Q PLANE PROJECTION

$$\begin{bmatrix} w_1 \\ w_2 \\ w_3 \\ w_4 \end{bmatrix} - \sqrt{\frac{3}{3}} \qquad \begin{bmatrix} 1 & 1 & 0.1 \\ 0.1 & 1 & 0.1 \\ 0.1 & 0.1 & 0.1 \\ 1 & 0.1 & 0.1 \end{bmatrix} \qquad \begin{bmatrix} p \\ q \\ r \end{bmatrix}$$

Figure 3-2. Skewed Sensor Geometry

A general aviation laser gyro AHRS is not currently available, but may become feasible. Honeywell is developing a laser gyro inertial reference assembly for the Boeing 767. Others are working on low cost laser rate sensors using optical fibers.

3.1.1.2 <u>PAAS Air Data Sensors</u> -- Dual solid state static and differential pressure transducers and dual temperature sensors are proposed for PAAS to provide fault tolerant inputs for computation of altitude, altitude rate, indicated airspeed and true airspeed. Honeywell's solid state transducers used in current commercial aircraft air data systems are representative of devices which will likely make the PAAS air data approach feasible in general aviation in coming years.

The Honeywell pressure sensor converts the applied pressure to a usable electrical signal. An N-type silicon diaphragm within the sensor contains two P-type resistors diffused in an orthogonal pattern on the diaphragm. The orthogonal placement of the resistors in the diaphragm creates a change in the bulk resistivity of the resistors that is a function of diaphragm tangential and radial strain. The trangential resistor ($\rm R_{\rm T}$) increases resistance with strain (applied pressure), while the radial resistor ($\rm R_{\rm R}$) exhibits a corresponding decrease with strain.

The silicon piezoresistors are, therefore, used as strain gage elements.

The resistive elements have nearly identical temperature coefficients of resistance, because they are formed at the same time during the processing operations and are adjacent to each other. This permits temperature-related errors to be largely self-compensating due to the sensor resistance-bridge circuit mechanization.

Sensed static pressure, differential pressure and temperature are converted to digital form and transmitted to the PAAS ADC processor for computation of altitude and airspeed signals for use on electronic flight instruments, and in PAAS autopilot and navigation functions.

3.1.2 PAAS Data Bus

The PAAS data bus is dualized for fault tolerance. One bus controller is located with each I/O terminal. The two busses operate continuously to provide dual redundant inputs to detect (and annunciate) faults with high confidence.

DAAS employs the 16-wire IEEE 488 8-bit parallel data bus. A high throughput serial data bus, for which LSIC interface components are available, is proposed for PAAS. The serial bus would be preferable to minimize aircraft wiring if the PAAS processors are packaged separately.

PAAS data bus throughput requirements have not been established, though PAAS data bus loading is clearly higher than DAAS because air data, AHRS data, and weather radar display data are added to the bus.

3.1.3 PAAS Computer Architecture

The PAAS computer employs the spare processor redundancy concept developed for DAAS, but extends back-up capability to all essential processors. See Figure 3-1. The PAAS spare can take over for any failed processor except the DABS processor, the weather radar processor, or the LDCC processor.

The DABS or weather radar function reliability would not be significantly enhanced by redundant processing because the higher failure rate sensors are not redundant. The IDCC back-up is a reversion mode on the EHSI display; thus IDCC processor backup is not required.

The PAAS processors receive their inputs, and supply outputs to dual I/O terminals via the dual PAAS data busses.

3.1,4 PAAS Displays

Proposed PAAS display configuration is illustrated in Figure 3-3. Three-color CRTs are included. One display normally presents:

- Attitude/Director Indicator
- IAS Indicator
- Altimeter
- Vertical Speed Indicator
- Etc.

The second panel mounted display is a horizontal situation indicator similar to the DAAS EHSI. A third display would be mounted in the pedestal for use as an IDCC.

The first display could be periodically switched to present the EHSI if the second display failed, and vice versa. The second display could also be switched to operate as a primitive NAV function IDCC if the primary IDCC failed.

Multifunction controls are provided for each display. The controls are relabeled when the display function changes.




Figure 3-3. PAAS Panel Concept

Communication control heads are panel mounted to provide tuning capability independent of the PAAS display system.

3.1.5 PAAS Servo Mechanization

PAAS servos are dual with clutch arrangements to allow switching between servos for continued operation after one servo failure. Each servo in a dual pair is driven from one of the dual I/O terminals. A servo model would be implemented in PAAS software for each mechanical servo, and model output would be compared to servo output to detect and isolate servo faults.

3.1.6 PAAS Power Mechanization

Dual, monitored power supplies are included in PAAS. The power references to the essential PAAS components are switched in event of a power supply failure.

3.1.7 PAAS Redundancy Management

PAAS would include extensive built-in test to detect and isclate faults to facilitate automatic reconfiguration. Fault detection confidence could exceed 99 percent for dual elements through use of simple comparison monitoring. Automatic fault isolation is feasible with confidence on the order of 80 to 90 percent for the dual sensors, and approaching 100 percent for the dual model-comparison-monitored servos.

PAAS could include capability for manual redundancy management as backup to the automatic fault localization/reconfiguration. The PAAS data bus could be switched manually from dual operation to Channel I or Channel II as indicated in Figure 3-3. Sensor and

servos could be manually selected on IDCC pages as shown in Figure 3-4.

3.2 PAAS RELIABILITY ANALYSIS

PAAS is configured to provide an order of magnitude improvement in functional reliability at a reasonable cost with respect to conventional architectures. Effectiveness of the PAAS architecture is therefore analyzed by comparing PAAS Autopilot and Navigation function reliability with respect to a hypothesized "conventional" system. The reliability analysis also compares the maintenance failure rate of PAAS and the "conventional" system to give some indication of PAAS relative life cycle cost.

The "conventional" system component list, and associated failure rates, are compiled in Table 3-1. This system includes current devices required to give functional capability similar to that of PAAS. Communications, navigation, flight control, performance computations, configuration monitoring, and weather radar are included. Where possible, failure rates are King Radio Corporation tabulations of actual operational experience. Honeywell Reliability Engineering Group provided generic estimates where operational experience was not available. The PAAS computer unit reliability prediction is extrapolated from the DAAS hardware mechanizations.

The "conventional" system maintenance failure rates are summed to determine a total failure rate of 1061.5 percent per 1000 hours, for a total system mean time between failure of 94 hours.

The "conventional" system autopilot/navigation functional reliability was determined by summing failure rates of components




Figure 3-4. PAAS Manual Redundancy Management

Table 3-1. Reliability Estimate for a Conventional System

DEVICE	FAILURE RATE (Z/100⊕ HRS)	QUANTITY	MAINTENANCE FAILURE RATE CONTRIBUTION (2/1000 HRS)	AUTO PILOT/NAV FUNCTION FAILURE EATE CONTRIBUTION (Z/1000 HRS)	CONSERT
NAV/FIT CONTROL SENSORS/INSTRUMENTS Yar Rate Gyro Magnetic Transmitter (KWT 112) Directional Gyro (KSG 105) Slave Control (KA 514) Vertical Gyro (VG 208) Pitot System, Left Pitot System, Left Pitot System, Right Encoding Altimeter (IN 571) Air Data Computer (KDC 180) VOR Receiver (KN 53) - DHI Receiver (KN 62A) Angle of Attack Sensor, Ind	5. 2. 33. 1. 33. 5. 5. 20. 20. 25. 50.	1 1 1 1 1 1 1 2 1	5. 2. 33. 1. 33. 5. 5. 20. 20. 50.	5. 0 33. 1. 33. 5. 5. 20. 20.	Manual slavin _e assumed if failed.
Turn and Bank Indicator OAT Sensor CONTROLS AND DISPLAYS Autopilot Mode Controller (KEC 350) Autopilot Annunciator Panel (KAP 315) ADI (KCI 310) USI (KPI 553) EMI (KI 226) Audio Control Panel (KMA 24) Failure Annunciator Panel Airspeed Indicator Artificial Horizon (KG 253) CONPUTER, ELECTROVICS	34. 3. 20. 20. 33. 20. 3. 28.	1 1 1 1 1 1 1	34. 25G. 34. 3. 20. 20. 20. 33. 2 3. 28. 67. 228.	15. 	Artificial horszon backup, degraded pertorman.e. RMI backup, degraded performance. USI backup.
Autopilot Coaputer (KAC 325) Flight Coaputer (KFP 320) RAAV System (RNC 655) VAAV Coaputer (KVN 355) Performance Computer	55. 85. 90. 45. 20.	1 1 1 1	55. 85. 90. 45. <u>20.</u> 295.	55. 85. 90. 45. <u>-</u> 275.	

ORIGINAL PAGE IS OF POOR QUALITY

Table 3-1. Reliability Estimate for a Conventional System (Sheet 2 of 2)

DEVICE	FAILURE RATE (Z/1000 HRS	QUANTITY	MAINTENANCE FAILURE RATE CONTRIBUTION (Z/10JO HRS)	AUTO PILOT/NAV FUNCTION FAILURE RATE CONTRIBUTION (Z/1000 BRS)	ee sterri	
SERVO ACTUATORS	7.	1	7.	7.		
Pitch Servo Roll Servo	7.	1	7. 7.	7. 7.		
Yaw Serve Pitch Trim Servo	7. 5.	1	7. <u>5.</u> 26.	7. <u>5.</u> 26.		
With LOSTING			20.	202		
MAP Sensor RPM Sensor Cool Flap Position	0.5 1. .5	2 2 1	1. 2. .5	- - -	Not required for Autopalet, MAV function.	
Flap Position Elevator Trim Postion Radar Altimeter	2. 2. 50.	1 1 1	2. 2. <u>50.</u> 57.5	- - - 0		
WEATHER RADAR			57.5	0		
Transmitter/Receiver Display Unit COMMUNICATIONS	50. 5.	1 1	50. 5. 55.	- 	Not required for Autopalot, RAV femilians.	
Cosa Transcrivers (KY 195) DABS Transponder DABS Control/Display	33. 40. 30.	? 1 1	66. 40. <u>30.</u> 136.	- - - - 0	Not required for Autopilot, NAV function.	
ELECTRICAL POWER SYSTEM			136.	U		
A/C 28VDT Bus, Aircraft Battery DC/AC Invertor DC/BC Converter	.11 1. 3.	1 1 1	NOT INCLUDED 1. 3. 4.0	1. 1. 3. 4.01		
TOTAL: 1056.5 4 6.51						
			HIBF = 94.6 HRS	201. URS		

required to provide these functions. Failure contribution of dual VOR receivers was considered negligible. The total conventional system autopilot/navigation function failure rate, assuming a 1-hour mission, is 496.5 percent per 1000 hours for a mean time between loss of function of 201 hours.

Corresponding PAAS maintenance reliability and autopilot/navigation function reliability are compiled in Table 3-2. PAAS maintenance reliability is 50 percent better than the conventional. system because:

- High reliability digital electronics employed
- High reliability solid state sensor technology employed
- Electronic displays replace conventional instruments
- PAAS integrated avionics architecture eliminates hardware

PAAS autopilot/navigation function reliability is improved by a factor of 50 with respect to the "conventional" system, primarily due to the fault tolerant PAAS architecture. A PAAS gyro, accelerometer or air data sensor failure can be tolerated without loss of a function. A PAAS processor failure, a power supply failure, and a servo failure can be tolerated without loss of function. This PAAS fault tolerance is accomplished with the minimum of redundant hardware, as described in section 3.1.

PAAS would suffer gross loss of function for certain failure combinations. For example, the PAAS configuration would be totally incapacitated by two like bus controller failures. The probability of such failures occurring during a 1-hour flight is extremely low, however; for example:

Table 3-2. Reliability Estimate for PAAS

DEVICE	FAILURE RATE (2/1000 HRS)	QUANTITY	MAINTENANCE FAILURE RATE CONTRIBUTION (Z/1000 HRS)	AUTO PILOT/NAV FUNCTION FAILURE RATE CONTRIBUTION (Z/1000 HRS)	क्टब्स
NAV/FLT CONTROL SENSORS					
Hagenetic Transmitter (KMT 112)	2.	1	2.	0.	. Hanual periodic heading alignment required if KHI IIZ fails.
Laser Gyro, Interface Electronics	5.	4	20.	2.	90% fault isolation capability assume.
Accelerometer, Interface Electronics	5.	4	20.	2.	90% fault isolation capability assumed.
Pitot System, Left	5.	1	5.	-5	90% fault isolation capability assumed.
Pitot System, Right	5.	1	5.	-5	90% fault isolation capability assumed.
Static Pressure Transducer	5.	2	10.	ì.	90% fault isolation capability assumed.
Differential Pressure Transducer	5.	2	10.	1.	90% fault isolation capability assumed.
VOR Receiver (KN 53)	25.	2	50.	0.	Manual switching if required,
DIE Receiver (KN 62A)	50.	1	50.	-	
Angle of Ettack Sensor	5.	1	5.	_	
OAT Sensor	2.	i	2.	.1	90% fault isolation capability assumed.
	1		179.	- <u>-1</u> 7.1	•
CONTROLS AND DISPLAYS					
Autopilot Node Controller (KHC 340)	34.	ì	34.	0	1500 page for backup.
EADI Display, Controls	35.	1	35.	0	Material switching of displays.
EISI Display, Centrols	35.	1	35.	0	Manual switching of displays.
IDCC, Display, Controls	35.	1	<u>35.</u>	<u>0</u> 0	Basic NAV page available on ENSI displays.
			139.	Ō	
COMPUTER, ELECTRONICS					
Processor (8086, Hemory)	6.	11	6 6.	1.8	Autopiler, MAV, ADC, AHRS, RAU, Bus Controller processors only, 95% fault isolation cujability assumed.
A/D, D/A, HUX	6.	2	12.	.6	95% fault issolution capability assumed.
Bubble Hemory System	50.	i	50.		Not required unless another failure occurs,
Buddle Helioty System	,,,	•	128.	<u>0</u> 7,4	ace requires anie is square across becomes
SERVO ACTUATURS			120.	2.4	
Pitch Servo	7.	2	14.	0	Servo-model comparison munituring for fault isolation.
Roll Servo	7.	2	14.	0	Servo-model comparison wonitoring for fault isolation.
Your Servo	7.	2	14.	0	Servo-model (temperison monatoring for fault isolation.
Pitch Trim Servo	5.	2	10.	0	Servo-model comparison monitoring for fault isolation.
			52.	ō	ERMAN DIVERSENAS

OF POOR QUALITY

Table 3-2. Reliability Estimate for PAAS (Sheet 2 of 2)

Sa√fice	FAIGURE SATE FAIGURE FAIGURE	qeani ity	Maintevance Failure Pate Contribution 12,1000 HRS)	AUTO PHAT NAV FENCTION FAILURE EATE CONTRIBUTION (2.1000 BRS)	
monitor afficient					
MAP MAP MAP Low: Frap Polystron Flap Position Elerator Tran Position Madar Altimetor (RT 221)	0.5 1. .5 2. 2. 55.	2 2 2 3	4. -5 2. 2. 53. 57.5	- - - - - 5	Nut required for Altopaco. NAV for tome
W-ATMER RALAK					
Tranum sterikeess	59,		<u>इत्त.</u> 53.	5	Not required for Autopolot, NAV tumotion.
sounder.					
Colas Tribicesperb (FF 191) GasBo Trunophilir	3 ° . 43.	ž L	66. <u>+7.</u> 105.	;	
<u> 18 - Ost - 18 D. 21800</u>					
A% 280% Ga , sectrant Ge ery PASS Battery Laser Gyro Power B.ppky De/US Converter	.01 16. 1. 3.	1 1 2	NGT INCLUDED 10. 1. 6. 17.	.61 6 1. -3 1.31	Pilot datangum on name by the one of PAAS Teasing must operate without bittery. 95% issuit addition capablishy assumed.
		1	UTAL: 728.5	10.8	
			MTSF + 137 NRS	9°to HR3	

Dual Failure Probability = $(\lambda_{BC} t)^2 = 1 \times 10^{-8}$

where:

 $\lambda_{\rm BC}$ = bus controller failure rate = 10%/1000 hours t = time = 1 hour

The two-failure probability is similar to the order of magnitude of Military aircraft fly-by-wire flight control catastrophic failure rate.

3.3 PAAS COST ANALYSIS

PAAS and "conventional" system cost estimates, compiled in Tables 3-3 and 3-4, indicate that the PAAS costs are similar to those for a conventional system.

The cost figures used in the analysis were current King Radio catalog prices where available, or rough estimates based on similarity where catalog prices were not available. The PAAS computer cost estimate is an approximation extrapolated from the DAAS hardware mechanization. No estimate is available for the PAAS laser gyro AHRS, so a cost number corresponding to an electromechanical device was used. Conclusions are not affected even if this number is significantly increased.

PAAS thus provides dramatic improvements in functional reliability without significantly increasing system costs. PAAS total costs are contained because PAAS is integrated and does not require dedicated controls and displays for its functions.

ORIGINAL PAGE 19 OF POOR QUALITY

Table 3-3. Cost Estimate for a Conventional System

Device	Quantity	Estimated Cost (Dollars)	Basis For Estimate
NAV/FLT Control Sensors			
Yaw Rate Gyro Magnetic Transmitter (KMT 112) Directional Gyro (KSG 105) Slave Control (KA 51A) Vertical Gyro (VG 208) Pitot System, Left Pitot System Right	1 1 1 1 1	1,200 205 2,495 60 4,303	Catalog Catalog Catalog Catalog Catalog
Encoding Altimeter (IDC 571) Air Data Computer (KDC 380) VOR Receiver (KN 53) DME Receiver (KN 62A) Angle of Attack Sensor, Ind. Turn and Bank OAT Sensor Subtotal	1 1 2 1 1 1	4,629 1,785 3,730 3,225 2,566 700 100 24,998	Catalog Catalog Catalog Catalog Catalog Catalog Catalog Estimate Only
Controls and Displays			
Autopilot Mode Controller (KMC 340)	1	885	Catalog
Autopilot Annunciator Panel (KAP 315)	1	520	Catalog
ADI (KCI 310) HSI (KPI 553) RMI (KI 226) Audio Control Panel (KMA 24) Airspeed Indicator Artificial Horizon (KG 253) Subtotal	1 1 1 1 1 1	5,610 7,200 2,205 675 170 1,250 18,515	Catalog Catalog Catalog Catalog Catalog Catalog Catalog
Computer, Electronics			
Autopilot Computer (KAC 325) Flight Computer (KCP 320) RNAV System (KNC 665) VNAV Computer (KVN 395) Performance Computer Subtotal	1 1 1 1	3,035 4,465 5,985 3,305 14,200 30,990	Catalog Catalog Catalog Catalog Catalog

Table 3-3. Cost Estimate for a Conventional System (Sheet 2 of 2)

Device	Quantity	Estimated Cost (Dollars)	Basis For Estimate
Servo Actuators			
Pitch Servo Roll Servo Yaw Servo Pitch Trim Servo Subtotal	1 1 1	2,140 2,140 2,140 1,665 8,085	Catalog Catalog Catalog Catalog
Monitoring			
Failure Annunciator MAP Sensor RPM Sensor Cowl Flap Position Flap Position Elevator Trim Position Radar Altimeter Subtotal	1 2 2 1 1 1	75 200 1,200 100 100 100 2,350 4,125	Estimate Only Estimate Only Estimate Only Estimate Only Estimate Only Estimate Only Catalog
Weather Radar			
Transmitter/Receiver Display Unit Subtotal	1 1	13,000 7,000 20,000	Split Estimate
Communications			
Comm Tranceivers (KY 196) DABS Transponder DABS Control/Display Subtotal	2 1 1	3,510 2,000 4,000 9,510	Catalog Estimate Only Estimate Only
TOTAL		\$116,223	

Table 3-4. Cost Estimate for PAAS

Device	Quantity	Estimated Cost (Dollars)	Basis For Estimate
Magnetic Transmitters (KMT 112) Laser Gyro, Interface Electronics Accelerometer, Interface Electronics Pitot System, Left Pitot System, Right Static Pressure Transducer Differential Pressure VOR Receiver (KN 53) DME Receiver (KN 62A)	1 2 2 2 1 1	205 8,000 800 800 3,730 3,225	Catalog Estimated of basis of cost of electromechan-ical replacement Estimate Only Estimate Only Catalog Catalog
Angle-of-Attack Sensor OAT Sensor Subtotal Controls and Displays	1	828 100 17,688	Catalog Catalog
Autopilot Mode Controller (KMC 340) EADI Display, Controls EHSI Display, Controls IDCC, Display, Controls Subtotal	1 1 1 1	885 7,000 7,000 8,000 22,885	Catalog Estimate Only Estimate Only Estimate Only
Computer, Electronics		0.000	Estimata Onlu
Processor (8086, Memory) Power Supply and Misc. A/D, D/A, MIX Bubble Memory System Subtotal	11 2 1	9,600 6,000 2,000 2,000 19,600	Estimate Only Estimate Only Estimate Only Estimate Only
Servo Actuators			
Pitch Servo Roll Servo Your Servo Pitch Trim Servo Subtotal	2 2 2 2 2	4,280 4,280 4,280 3,330 16,170	Catalog Catalog Catalog Catalog

Table 3-4. Cost Estimate for PAAS (Sheet 2 of 2)

Device	Quantity	Estimated Cost (Dollars)	Basis For Estimate
Monitor Sensors MAP RPM Cowl Flap Position Flap Position Elevator Trim Position Radar Altimeter (RT 221) Subtotal	2 2 1 1 1	200 1,200 100 100 100 2,350 4,050	Estimate Only Estimate Only Estimate Only Estimate Only Estimate Only Catalog
Weather Radar Transmitter/Receiver Subtotal Communications		13,000 13,000	Transceiver/display Split Estimate
Comm Transceivers (KY 196) DABS Transponder Subtotal TOTAL	2	3,510 2,000 5,510 \$98,903	Catalog Estimate Only

3.4 PAAS MAINTAINABILITY ANALYSIS

The projected advanced Avionics System (PAAS) maintenance test concept is depicted in Figure 3-5. Highly effective avionics built-in test (BIT) is anticipated. On-aircraft functional testing and fault localization to a module within an LRU are expected to be feasible with minimal test equipment. The fixed base operator could exploit the BIT capability and minimize his special purpose test equipment and become more a storehouse of replaceable modules. The avionics should include capability for onaircraft trouble shooting by the fixed base operator. Faulty modules could be repaired at the factory.

BIT design objectives consistent with the above maintenance philosophy are:

- Minimize fixed base operator test capability requirements
- Maximize BIT fault localization capability

Of course, the resulting BIT mechanization must not significantly increase avionics cost.

DAAS BIT modes include:


- In-flight test
- Functional test/fault localization automatic
- Functional test/fault localization interactive
- Maintenance trouble shooting

In-flight-test is continuous and will generate a warning when a detected failure will disable a system function. The DAAS will automatically reconfigure for computer unit processor failures.




ON AIRCRAFT MAINTENANCE

- FUNCTIONAL TESTING 95% CONFIDENCE
- FAULT LOCALIZATION TO LRU 90% CONFIDENCE
- FAULT LOCALIZATION TO REPLACEABLE MODULE 80 – 90% CONFIDENCE
- TESTING, TROUBLESHOOTING VIA IDCC



FIXED BASE OPERATOR

- ON AIRCRAFT MAINTENANCE
- LIMITED GENERAL PURPOSE TEST EQUIPMENT
- REPLACEABLE MODULE STOCK
- IRU STOCK - - (LIMITED RENTAL UNITS)



DEPOT/FACTORY

- MODULE, LRU ATE
- STANDARD LRU ATE BUS INTERFACE
- MODULE, LRU REPAIR
- SPARE PARTS STOCK

Figure 3-5. PAAS Maintenance Concept

In-flight failures that are detected by BIT will cause the amber warning light to flash. A message will be displayed on the IDCC on the line reserved for warning messages. The message will be, "Device Failure" followed by identification of the failed device. (Vertical Gyro, Compass, etc.).

Functional Test/Fault Localization, Automatic, is performed at power-up, or when commanded by the operator, and tests system components as feasible without operator interaction. This test function exercises DAAS equipment and identifies failed LRUs as well as failed modules within the LRU as reasible.

Functional Test/Fault Localization, Interactive, is performed on command and allows testing of devices where operator actions or observations are necessary to complete a test. IDCC and EHSI test pattern tests are included in DAAS as examples of avionics interactive testing.

Maintenance trouble shooting allows the operator to apply signals and measure signals via IDCC. Memory words can be displayed. Analog and discrete signals can be applied at computer outputs, and various system analog and discrete signals can be measured and displayed.

Fault localization and replacement of a faulty avionics line replaceable unit can be accomplished in mean time of 15 minutes with the level of BIT envisioned for PAAS. Repair of a faulty unit, i.e., fault localization and replacement of a faulty part, can be accomplished in mean time of 1 hour.

PAAS packaging must be designed to allow operator removal of hardware modules and continued operation with only partial loss of function.

3.5 PAAS MODULARITY ANALYSIS

PAAS is designed to be modular. The system is constructed of building blocks that can be configured to provide varying levels of functional capability depending on user requirements. The design is intended to facilitate addition of functions without major upheaval to the existing aircraft control panel or existing avionics.

Modularity is achieved through:

- System architecture
- Controls and displays modularity
- Hardware modularity
- Software modularity.

Basic system architecture, i.e., multimicroprocessors interconnected via data bus, supports modularity. Functions can be added by adding appropriate process or modules, and the processing can interface to the system through the data bus.

PAAS employs programmable controls and displays that can be reconfigured for various functional complements. The IDCC includes basic mechanical controls (keyloard page callup buttons, etc.) and a programmable display. The basic display module is the display page. The page can be used as a function control panel or for required data and information input/output. The EHSI and EADI are displays that can be programmed for the set of functions included in a particular PAAS installation.

PAAS hardware is modular. Standard modules can be added to provide computing power, memory, or I/O required for added functions.

PAAS software is structured and modular. Each of the hardware modules are programmed with independent software modules that require minimum interfaces with other functions. These software modules are developed using structured design techniques. The system modularity has been demonstrated by addition of the DABS function.

The integration of DABS into DAAS late in the DAAS development program demonstrates basic modularity. Incorporation of DABS required --

- Installing a DABS transponder in the aircraft, and interfacing it to the DAAS computer unit.
- Adding a DABS processor module, including software, and two DABS interface electronics modules to the DAAS computer unit.
- · Adding three DABS pages to the IDCC.
- Adding a DABS "Message Pending" light to the panel.

The DAAS processor module is appropriate for DABS computations. DAAS keyboard and IDCC page formats are appropriate for DABS. Consequently, DABS readily fit into the DAAS framework. PAAS modularity is further assessed in the following paragraphs.

3.5.1 PAAS System Modularity

PAAS system modularity is demonstrated in Figure 3-6. The various levels of functional capability are depicted. The core PAAS functional entity is the autopilot.

The autopilot processor and a basic I/O terminal are required for this function.




Figure 3-6. PAAS Modularity

A second version of PAAS could include the autopilot and the air data functions. In this version, the air data function would only supply references for the autopilot. Altimeter and IAS data sources would be independent.

A third version of PAAS could have autopilot, air data, AHRS, and the electronic ADI that includes the altimeter, IAS and VSI displays.

A fourth version could also include the NAV, EHSI and IDCC functions.

A fifth version could have DABS added, and a sixth version could include weather radar data superimposed on the EHSI.

A seventh version could include the necessary redundant hardware for fault tolerant operation.

Each version of PAAS would be complimented by systems necessary for desired functional capability and backup. A particular version of PAAS could include spare room to allow incorporation of some additional capability: either the defined next higher level, or a yet-to-be-defined advanced capability.

3.5.2 PAAS Controls and Displays Modularity

The ideal controls and display configurations from a modularity standpoint, would include only general purpose controls. No controls dedicated to a specific function would be allowed in order to minimize impact on panel hardware when a function was added. In an inealized PAAS configuration, controls would include a general purpose keyboard, and one IDCC page callup button for each function.

DAAS has deviated from this ideal in certain respects:

- Various dedicated NAV function controls are implemented above the IDCC, included with page call-up buttons; i.e., USE, CRS, SEL, LAT DIR TO, AUTO CRS SEQ.
- Dedicated map control buttons are implemented next to the IDCC; i.e., HDG/NOR, MAP/CRSR, MAP RTN, WP BRG, REVU, MAP SCALE.
- Dedicated autopilot mode controller, annunciator panel.
- Other function controls

These dedicated function controls were implemented to maximize their accessibility.

Dedicated NAV function controls could be avoided if these controls were instead implemented in IDCC pages. The penalty for elimination of dedicated NAV function buttons is as follows:

- One additional button push required to activate LAT DIR TO.
- One additional button push required to change waypoint data access from linked waypoint, to unlinked waypoint.

The advantage of this approach, in addition to improved modularity, is elimination of dedicated NAV function buttons above the IDCC, which leaves only page call-up buttons there. This eases system comprehension.

Current dedicated map control buttons do not significantly degrade modularity. They can be an integral part of the EHSI assembly. Spare control buttons should be included, however, for additional

functions which use the EHSI, which will also have dedicated controls; e.g., weather radar.

The PAAS Autopilot mode controller is a dedicated panel. Accessibility to the safety critical mode controller seems to preclude its incorporation into multifunction control facilities such as the IDCC. The autopilot mode annunciator panel would likely be incorporated into the EADI if EADI were included in PAAS.

3.5.3 PAAS Hardware Modularity

The existing DAAS hardware is modular. The basic hardware building block is the processor board, Figure 3-7. This 6.25 by 6.25 inch printed circuit board includes:

- INTEL 8086 16-bit microprocessor
- 2K x 16 PROM Memory
- 4K x 16 RAM Memory
- Crystal clock
- IEEE 488 bus talker/listener/controller
- Interrupt controller

If more than $4K \times 16$ memory is required for a particular PAAS processor, a supplemental 6.25 by 6.25 inch memory board is used. This memory board can contain up to $12K \times 16$ additional RAM memory. Other hardware modules that could be employed in a PAAS system include:

- EADI, EHSI display refresh memory module
- Bubble memory module
- Analog/Discrete I/O modules




Figure 3-7. DAAS Processor Module

PAAS would employ a higher level of circuit integration than the existing DAAS system. Custom VLSIC would be economical for PAAS for the basic hardware modules. Exploiting modularity of a production version of PAAS requires the following hardware design considerations:

- The PAAS computer box must have sufficient room and external connector pin capacity to support eventual growth.
- Power supply The PAAS power supply must have reserve capacity to support eventual system growth or else the power supply must be changed as functions are added.
- Data bus throughput The PAAS data bus must have sufficient throughput margin to support eventual system growth. The current system IEEE 488 bus is only 30 percent loaded, which is consistent with this requirement. The PAAS data bus would require higher throughput to accommodate the AHRS and weather radar functions.

3.5.4 PAAS Software Modularity

PAAS software must be modular. Functions are implemented in software modules; i.e., independent programs with single entry and exit, separate data locations and clearly defined and controlled interfaces. Data bus communications are managed in an orderly fashion by the bus control processor, with growth in mind.

SECTION 4 CONCLUSIONS AND RECOMMENDATIONS

The DAAS system design is completed, and flight hardware built. Simulator evaluations have been performed. The PAAS configuration has been defined and analyzed on the basis of cost, reliability, maintainability, and modularity. The following conclusions and recommendations are based on the experience associated with this effort to date.

- Functional Configuration DAAS provides expanded functional capability with respect to currently available avionics and has the potential to significantly improve single pilot IFR safety and efficiency. The DAAS architecture provides the framework for additional expansion without the requirement for added displays. This is accomplished by using the shared data base, displays and bus. The distributed architecture of the system provides for functional independence. This minimizes the number of needed interfaces between functions and thereby reduces data input and subsequent pilot training.
- Function Set The DAAS function set is comprehensive and suitable for demonstration. Operational simplification and functional additions have been suggested that may be appropriate for an operational system.
- Cost The DAAS concept is cost effective, and has cost advantages with respect to conventional avionics as the number of integrated functions increase.

- Reliability The DAAS system architecture reduces computer system failure rate to a negligible portion of the total system failure rate. Sensor and servo failure rates dominate. Low cost sensor and servo redundancy should be pursued with a goal of 10,000 hours in-flight MTBF for autopilot and basic navigation functions to provide extremely reliable pilot relief to facilitate effective flight management. The PAAS configuration promises much higher functional reliability.
- <u>Maintainability</u> DAAS offers improvements in avionics maintainability through improved reliability, automatic fault detection and isolation, and on-aircraft trouble shooting without special test equipment.
- Modularity DAAS is functionally modular, with general purpose controls and displays, and hardware and software building blocks to provide varying levels of capability. Expansion of capability has minimum impact on the existing aircraft control panel and existing avionics.

Following is an expansion of these conclusions and recommendations.

4.1 FUNCTIONAL CAPABILITY

The DAAS system provides comprehensive facilities for flight management. Concensus of evaluations is that DAAS provides improved functional capabilities with respect to current avionics, and has the potential to significantly improve single pilot IFR efficiency and safety. Checklists, weight and balance, and performance functions are convenient to use, and they support good pilot practices. The moving map display, IDCC data readout, and

comprehensive warning system inform the pilot of flight status. The autopilot, which couples to the NAV system, provides the necessary relief that allows the pilot to monitor and effectively manage his flight.

The DAAS moving map display is well received and considered a major aid in flight management. However, the following enhancements have been suggested:

- Terminal area display should be expanded to include stored approach plate details. Automated terminal area flight management including coupled NAV and autothrottle functions should be considered.
- It would be desirable to accurately display the runway during landing approach. This could, perhaps, be feasible if 1) a strapdown AHRS with short term INS capability were a part of DAAS, or 2) MLS were included, or 3) GPS were included, or 4) ILS/DME navigation mode were included.
- A color map display would be useful to facilitate increased display information content.
- Expansion of DABS to aid in congested terminal area communications would be desirable.
- Incorporation of an EADI into DAAS would be an appropriate follow-on effort to further develop the concept.

The DAAS function set is considered representative and adequate for demonstration purposes. There are areas where changes might be considered for an operational system. For example, DAAS complexity must be controlled and pilot/system interface must be efficient to maximize pilot access to DAAS functions.

DAAS controls and displays have been generally accepted by evaluators, including the alphanumeric keyboard. The system simulator IDCC touchpoint mechanization was found objectionable because:

- No tactile feedback to indicate signal initiation.
- Smudges on CRT face obscured image.
- Inadvertent data entries possible if touchpoints are not accurately touched.

An alternate approach using bezel-mounted buttons has been added.

The DAAS Kalman filter blending of VOR/DME data with dead reconing position is expected to improve navigation, precision and stability. The addition of DME/DME integration into the DAAS algorithms seems like an appropriate follow-on. Integration of an IRS to augment the blender position should also be considered.

4.2 COST

DAAS includes significantly more functional capability at a cost competitive with conventional avionics, as illustrated in section 3.3. The DAAS cost advantage will become more decisive as more functions are incorporated. For example, DAAS could be expanded to integrate:

- Weather radar
- Air data computer
- Autothrottle
- Automatic storage of airport facility data

- AHRS
- Radar altimeter
- Other functions

Therefore, with each function added total system cost per function would come down since packaging power supplies, and controls and displays are shared in DAAS and need not be duplicated for separate functions.

Consequently, the DAAS concept of integrated avionics is cost effective.

4.3 RELIABILITY, SAFETY

The PAAS system reliability, including sensors, instruments, computers, and servos is estimated to be 137 hours MTBF. This system reliability is expected to improve as integrated circuit technology advances, and electromechanical devices are replaced by solid state devices.

The existing DAAS NAV/Autopilot function reliability is estimated to be 9260 hours mean flight time between loss of function.

The DAAS architecture, using advanced electronics, has produced a very reliable computer system. Consequently, DAAS reliability was affected mainly by sensor and servo failure rates; e.g., system sensors and servos contribute 96 percent of the autopilot failure rate. Since the autopilot and NAV functions are essential to effective flight management, it is recommended that low cost redundant sensor and servo configurations be pursued, with

a goal of 10,000 hour NAV/autopilot flight MTBF. The DAAS architecture can cost effectively provide such reliability.

The failure mode effects analysis of 86 DAAS elements concludes that, with recommended modifications implemented, DAAS failures are tolerable and safe. The DAAS safety pilot's contribution to flight safety is also acknowledged, especially in take-off and landing situations.

4.4 MAINTAINABILITY

DAAS concept offers improved maintainability through:

- Improvements in hardware reliability
- Built-in test for automatic fault detection, localization
- Capability for on-aircraft trouble shooting without special test equipment.

4.5 MODULARITY

The DAAS system is functionally modular. It is composed of hard-ware and software building blocks that can be configured to provide varying levels of functional capability and cost. Expansion of capability will have minimum impact on the existing DAAS air-craft control panel and avionics.

The DAAS system can be adapted to interface with devices from a variety of manufacturers. For example, hardware and software modules could be developed to allow use of different NAV receivers,

even if the NAV receivers were not equipped for remote tuning. Manual tuning would be required in this version of DAAS, on command from the IDCC. The system can also accept input signals from sensors supplied by a variety of manufacturers. The variety of subsystems with which a production version of DAAS would be compatible would be determined in a marketing study.

DABS integration into DAAS late in the DAAS development program demonstrates basic modularity. Incorporation of DABS required:

- Installing a DABS transponder and control panel in the air-craft, and interfacing it to the DAAS computer unit.
- Adding a DABS processor module, and two DABS interface electronics modules to the DAAS computer.
- Adding three DABS pages to the IDCC.
- Adding a DABS "Message Pending" light to the panel.

The DAAS processor module is appropriate for DABS computations. DAAS keyboard and IDCC page formats are appropriate for DABS. DABS readily fit into the DAAS framework, thereby demonstrating that DAAS is a highly modular system.

GLOSSARY

ADI - altitude direction indicator

AHRS - Altitude Heading Reference System

ALT - altitude, altitude hold

ARM - arm

ATC - Air Traffic Control (National)

BIT - built-in test

CC - central computer

CCU - central computer unit

COM - communication

COMM - communication message

CPU - central computer unit

DAAS - Demonstration Advanced Avionics System

DABS - Discrete Address Beacon System

DME - distance measuring equipment

EHSI - electronic horizontal situation indicator

ELM - extended length message

EPROM - electrically alterable PROM

ETA - estimated time of arrival

FAR - federal aviation regulation

FDI - flight director indicator

GMT - Greenwich mean time

GS - glideslope

GLOSSARY

HDG - heading

IAS - indicated air speed

IDCC - integrated data control center

IFR - instrument flight regulations

LOC - localizer

MDA - minimum descent altitude

MLS - microwave landing system

NAV - navigation

NAVAID - navigational aid

PAAS - Projected Advanced Avionics System

PROM - programmable read-only memory

RAM - random access memory

RAU - radio adapter unit

RMI - radio magnetic indicator

ROM - read-only memory

RPM - revolutions per minute

SEL - select

SM - standard message

UV - ultra-violet

UV-EPROM - ultra-violet eraseable PROM

VFR - visual flight regulations

VHF - very high frequency

GLOSSARY

VNAV - vertical navigation

VOR - VHF omnidirectional (omni) range

VOR/LOC - VOR localizer

VOR/LOC/GS - VOR localizer glideslope

VSI - vertical speed indicator

APPENDIX A PROFILES OF DAAS TEST PARTICIPANTS

SUBJECT PROFILE #1

Name: Bill Unternaehrer

Position: Design Engineering, Honeywell, Inc.

Number of Years Active Flying: 13 years

Certified Flight Instructor: Yes

Ratings: ATP, MEL, Commercial, SEL, SES, Glider

Flight Instructor - Instrument and Airplane

Experience with HSI; Yes (20 hours)

Aircraft Flown Flight Hours

Piper (Single & Twin) 550

Cessna (Single) 1500

Currently Fly: Cessna

PRECEDING PAGE BLANK NOT FILMED

SUBJECT PROFILE #2

Name: Larry Pedersen

Supervisor, Test Equipment Field Engineering., Position:

Honeywell, Inc.

Number of Years Active Flying: 15 years Certified Flight Instructor: Yes

Ratings: ATP, Airplane and Power Plan Mechanic

Flight Instructor - Airplane and Instrument

Experience with HSI: Yes (King HSI)

Aircraft Flown	Flight Hours
Cessna (Single & Twin)	825
Beech (Single & Twin)	205
Piper (Single	800
Others 20	20

Currently Fly: Beech Bonanza, Cessna 172, Cessna 421

SUBJECT PROFILE #3

Name: Ron Albertson

Position: Pilot, King Radio Corp.

Number of Years Active Flying: 12 years

Certified Flight Instructor: Yes

Ratings: MEL, ATP, Gold Seal

Flight Instructor - Airplane and Instrument

Experience with HSI: Yes (KFC 300, KFC 200, KFC 250,

Bendix 810, Mitchel)

Aircraft Flown	Flight Hours
Beech	3,000
Piper	3,000
Cessna	3,000
Bellanca	3,000
Mooney	3,000

Currently Fly: All above

SUBJECT PROFILE #4

Name: John Lindberg

Position: Pilot, Instrument Flight Training

Number of Years Active Flying: 10 Certified Flight Instructor: Yes

Ratings: MEL, ATP

Flight Instructor - Airplane and Instrument

Experience with HSI: Yes (KFC 300, KFC 200, Collins Bendix, Narco)

Aircraft Flown Flight Hours Beech 1,000 Piper 1,000 Cessna 1,000 Bellanca 1,000 Mooney 1,000

Currently Fly: All above

SUBJECT PROFILE #5

Name: Dan Rodgers

Position: Director Special Projects; King Radio

Number of Years Active Flying: Certified Flight Instructor:

Ratings: MEL, Private Instrument

Experience with HSI: Yes, Project Engineer KFC 300 and KFC 200

Aircraft Flown Flight Hours

Beech Not available
Piper Not available
Cessna Not available
Mooney Not available

Currently Fly: All above

APPENDIX B DAAS FAILURE MODES AND EFFECTS ANALYSIS


FAILURE 110.	DAAS ELEHENT	110.		FAILURE RATE* Nº	AFFECTED ELEHENTS	EFFECTS OF FAILURE	DAAS WARN.	ETC.	FAILURE CATEGORY	CU+tcTS
1	Encoding Alti- meter	-571	Fault within the Altim.	200	Altimeter Indicator	Erroneous Visual Output	sos, P Servo		3	Buring IFK-conditions. Proximity warm. no not netect. Vertical bustacles
					Dabs Transpond. KT76A "	Erroneous Output	Error Amber		3	Hisleads Traffic Control.
					A/P CPU	Erroneous			3	
						"G. Proximity Warn."				Wrong Warn. Turesuold
					A/P & TUCC CPU	Erroneous "Alt. Advisory" Light Info. (Alt. Alert, HDA & DH.)			2	"Secondary Effect"
					A/P & NAV CPU	Erroneous Parameter T.O. & Nav. Calculation			3	brong fuel or T.U Distance Calculation.
			Conclusion	The Pr	robability for a f	edundant altimeters for Cat. ailure is ~ 10 ⁻³ during 4 hour ation required in DAAS. OK.				
2	Co-Pilot Altimeter		Fault in the Altimeter	200	Altimeter Indicator	Erroneous Visual Output	lia		2	Will cause some inconven- ience until decided which altim. failed.

Conclusion: Loss of the co-pilot altitude info is a minor problem to the DAAS pilot. The probability of loss of both bero-altimers during 4 flt. hrs. is: λ^- (λ pitot + λ altim)pilot - (λ pitot + λ altim)co-pilot - (4-250-10⁻⁶) - 10⁻⁹. A catastrophe will occur if the A/C collides with an object not detected by the proximity warning system. The probability for this to happen is considerably less than 10⁻⁸.

Allude HU.	Trailala Cond	nd.	FAILURE	FAILUKL KMTL*1J ⁶	AFFECTED ELEHENTS	EFFECTS OF FAILURE	umms Harii. LTC.	FAILUKL CATEGURY	CUFTATS
j	Kadar Altimeter	KT251	Fault in Rau. Alt. Incl. Ant.	ექს	A/P CPL & TUCC A/P CPu & EdST	Erroneous "G. Proximity Narn." Erroneous: Nad. Alt. Info.	Rad. Alt. Valid. (Amber Light)	ž	Ine protability «<10-6 for Waroand Madar-Altim. Failures
			Conclusion	- A crit		n Rad. Alt. if installed, fai occur if both the daro. Alt OK.			ity signal üK.
4	True Air Speed Sensor	V#210	Fault in Tas OR Sign. Cond	100	A/P & Hav. CPU EHSI	Erroneous inputs to Nav. & Fuel consum. calculations	ilo -	2	Pilot confused. Hight create a problem if no radio May. available.
			Conclusion	It is		91. p ⁻⁶) that a TAS failure will of VOR/DHE information.	cause a critica	l situatio	n in UAAS
5	IAS Instru- ment	Pane1	Instru- ment Failure	280	IAS Indicator	Erroneous visual output	Ho	2	
			Conclusion			K for Cat 1 IFR, Far 91. 2 re not critical in DAAS. Redund			
6	Co-Pilot IAS Instru- ment		Instru- ment Failure	280	IAS Indicator	Erroneous visual output	lio	1	Heglectable to pilot. Redundant info. available (IAS + KPH)
			Conclusion	The pr (4 330	obability of loss $(-10^{-6})^2$ $-2 \cdot 10^{-6}$.	fo. no problem to the pilot. of both IAS indicators are (The risk for a catastropne i info. such as VOR/DME and an	s significantly	lower in	the uAAS
7	Air Data Computer	KDC- 380	Instru- ment Failure	200	A/P CPU	Erroneous a-H Signal	Yes Alt. Valid (Amber Light)	2	Additional Alt. & YS info. available. The pilot monitors Alt. nolu.
			Conclusion			ire a 3rd IAS/ALT. Sensor. available redundant info. wil	l winimize risk		

ORIGINAL PAGE IS OF POOR QUALITY

FAILUKE	NAAS ELEMENT	иU.	FAILURE	FAILURE KATL*10 ⁶	AFFECTED ELEMENTS	LFFECTS OF FAILURE	UAAS WARHLETC.	FAILURE CATEGURY	CutiMents
ಕ	Pitot System	left	Faulty PTOT or PSTAT	5ù	Altimeter VSI-indicator IAS-indicator ADC KUC-380	Erroneous: ALT & A-H info. IAS & VSI flight warning proximity " transponder response	NO	3	Confusing info. Risk for wrong action in IFR cond. Pilot or ground control.
9	Co-pilot			••					
	pitot system	right	faulty PTOT or PSTAT	50	Altimeter VSI-indicator IAS-indicator	Erroneous visual info. to co-pilot	NO	1	Co-pilet not in the control loop.
			Conclusion	PI IUI S	vstem provide ade	red by FAR 91 only for CAT. I quate redundancy. Hity of failures in both left		-	
10	Outside air temp.		sensor or sign. cond. failure		NAV-CPU	Erroneous input to T.O., cruise, and fuel/distance calculat.	kÜ	2	fuel qty. cnecks will alarm pilot in time for refueling. Probability of failure low
			Conclusion	uAT fai	required by FAR. lure is not assum puts to calculatio	ed to cause severe pilot prob ons such as OAT ALT etc. are o	lems. It is s displayed to t	uggested, however, he pilot when used.	



FAILURE	UAAS ELEHENT	dO.	FAILURE	FAILURL RATL*10 ⁶	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARN. ET	FAILURE C. CATEGORY	CulticuTS
11	Hagnetic Flux Detector	त्रभा 112		20	Radio Magnetic indicator and EHSI	Erroneous Visual Output. (Dir. GYRO slaved to Mag. Fx. Det.)	но	3	The pilot misled by 2-3 indicators giving consistent faulty information.
			······································		A/P - CPU	Faulty Hdg. Error in Hdg-hold mode		3	ЮПП12 essential unit!
					HAV - CPU IDCC-CPU	Faulty Navigation and fuel/distance calculations		3	Kalman Filter will output excessive wind, spoiling calculations.
			Conclusion:			indicator and dir. GYRO for I . compass makes DAAS ok!	FR. 2 dir	. GYROS req. for	Cat II cond.
12	Slave Acces-	KA 51A	Dead or . wrong output	10	The indicator	Faulty visual output	Ho	1	RHI and way, cowpass info available to pilot, eliminates confusion.
			Conclusion:	Far ±1 do	not explicitly s	tate the need of a slave acce	ssory.		
13	birectional GYRC including Scott T/DNA	KSG 1J5	Faulty idg. Uut- put	300	Radio magnetic indicator and ENSI	Erroneous visual output	Yes Ildg. val (Amber L		Dir. GYRO essential. See See No. 11 connents.
					A/P - CPU	Faulty Hdg. Error in Hdg. Node			
					HAV - CPU	Faulty navigation and fuel/distance			
					IDCC-CPU	calculations			
			Conclusion:	The Dir.		t coverage ~ 70%. Probabilit flight. Still significant!	ty for unde	etected fallure ((U.J-4 - 3vú·10 ⁻⁶)
14	Radio magnetic	KZ	Fault in	330	RHI indicator	Erroneous visual output	ılo	2	Mag. compass, PMI and EMSI provides redundant info to
	indicator	226	the RIII		GYRO or VOR mode	•			pilot.

Conclusion: Far requirement see No. 11. OK.

FAILURE	DAAS ELEMENT	иO.	FAILURE	FAILURE RATE*106	AFFECTED ELENENTS	EFFECTS OF FAIL	URE	DAAS WARN. ETC.	FAILURE CATEGORY	CONFERTS
15	Co-Pilot Hag. Flux Detector		Faulty Mag. North Ref. Signal	20	PHI (Slave Acc.)	Erroneous Visua	1 Output	ila j		
16	Slave Aceessory	КА 51А	Bead or Wrong Output	10	Slave Acc.	Erroneous Visua) Output	No	> 1	l to the pilot
17	Directional GYRO	KG 102A	Faulty Hdg. Output	300	PHI (Slave Acc.)	Erroneous Visua) Output	Но		(2 to co-pilot)
ld	Pictural Nav. Indicator (P.N.I.)	KI 525A	Mag. Card Error	330	₽nI	Erroneous Visua	1 Output	No J		
			Conclusion:	The proba	co-pilot slaved din bility of one fai in the co-pilot sy: wass and VOR info.	lure in the pilot stem is [4.660.10	slaved direct -6 2 <105	ctional GYRO: The probabil	system and or	ne
19	Turn and Slip Instrument	"RC Allen"	Faulty Turn Rate	150	Turn Rate Indicator	Erroneous Visua	1 Output	lio	1	Turn rate determined from roll angle as replacement
			Instrument Faulty Slip Instrument	10	Slip indicator	es 16	•	No	1	Side acceleration sensed by pilot acceptable replacement.
			Conclusion:		ip-skid indicator this instrument mi		. I and II I	FR, By Far 9	1.	
20	Co-Pilot Turn and Slip		Faulty Turn Rate	150	Turn Rate Indicator	Erroneous Visua	1 Output	No	1	
	Instrument		Instrument Faulty Slip Instrument	10	Slip Indicator	Erroneous Visua	l Cutput	Но	1	
			Conclusion:	liegl igibl	le to the pilot and	d co-pilot.				

OF POOR JUSTIN

Conclusion: Far 91 requires 1 "Artifical Horizon" for Cat. I conditions and 2 for Cat. II.

Ine coverage of the validity test is ~ (0.3-4-330-10⁻⁶) ~ 4-10⁻⁶ significant!

Far 23.1329 e) a hardover failure in the vertical GYRO roll output propages via the A/P cont. laws to roll, yaw and pitch axis. This is not acceptable to far 91 wording.

A mudification to eliminate the Far-conflict is recommended.

142

FAILURE NO.	UMMS ELEMENT	ıω.	FAILURE	FAILURE RATE*106	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARN. ETC.	FAILURE CATEGURY	Cutstails
24	Attitude Dir. Indicator "Artifi. Hori."	кСІ 310	Faulty "Artif. Horizon"	340	"Artifi. Horiz." Indicator	Faulty Visual Output	Но	2	A/P modes and redundant info available.
			Conclusion		uirements, see fac S is OK in this re				
25	Co-Pilot "Artifi. norizon"	KG 258	Fault in "Artifi. Horizon" Unit	670	"Artifi. Horiz." Indicator	Faulty Visual Output	Ho	1	The DAAS pilot can easily determine that the kuzod is faulty. Several redundant indicators available to him.
			Conclusion		or snows if "power	lficial Horizon is a mino r" is available and provi			
				flight of both	1s - 4 . (330 + 34)	llures in both vertical 6 0) • 10 x 4 •670• 10 zons" is not negligible	or 7 -10 - The r	isk for loss	during a 4 hr.
∠υ	Hanifold Pressure Instrument	Pane1	Instrument Failure	ไป	Map Indicator	Faulty Visual Output	Но	2	In case of ap instrument failure these instruments and audiovisual feed backs
27	Engines RPM Instrument	Pane1	Instrument Failure	10	RPM Indicator	Faulty Visual Output	llo	2	provide enough info. to the pilot to allow correct failure localization.
28	Exh. Gas. Temp. Instr.	Panel	Instrument Failure	10	LGT Indicator	Faulty Visual Output	Но	2	
29	Engine Status Instrument 2	Panel	Low Oil Pressure or High Temp.	10	Eng. Status Indicator I	Faulty Visual Output	Ho	3 }	Faulty indication of low oil pressure may during some conditions force the pilot to shut off the
30	Engine Status Instrument 2	Panel	Low Oil Pressure or High Temp.	10	Engine Status Indicator 2	Faulty Visual Output	. iio	3	engine and land A.S.A.P.

Conclusion: Far 91 requires with exception of the EGT, the engine instrumentation. Listed above. (YFR conditions). DAAS independent of these instruments.

FAILURE NO.	DAAS ELEHENT	110.	FAILURE	FAILURE RATE*106	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARN. ETC.	FAILURE CATEGORY	CORSENTS
31	Fuel Flow Sensor 1		Faulty Sensor	5	Fuel Flow Indicator	Faulty Visual Output	No	2	Fuel Uty. Info. available
					IDCC	Faulty IDCC info: "Fuel Remaining Time" "Estim, Fuel Remaining"	No	2	"Estim, Fuel Remaining" may indicate too much left, which will mislead the pilot.
			Conclusion	A fault Fuel qu	ty sensor might r ty. cross checks	fuel flow sensor. esult in a pilot decision to may not reveal the situation flight safety critical situ	. It is a low p	tht without probability	sufficient fuel. (<10 ⁻⁶) that tne
32	Fuel Flow Sensor 2		Faulty Sensor	5	IUENT	ICAL TO FAULT NO. 31.			
33	Fuel Uty.	Panel	Faulty Sensor L or R	150	Fuel Uty. Indicator	Faulty Visual Output	llo	2	DAAS provides independent and redundant info. re- garding remaining fuel.
			Conclusion	fuel/d		y. instrument for VFR condit ulations, which improves the			
34	hanifold Pressure Sensors	Cele- sco	Faulty Sensor	5	A/P - CPU	Warning + No Hap Fault Amber Light No Warn. + Hap Fault	tio	1	Redundant engine instru- ments provides adequate info.
35	Engine RPH Sensors and F/V Converter	IJASA	Faulty Sensor	10	A/P - CPU IDCC Light	Warning + Ho RPH Fault Amber Light Ho Warning + RPH Fault	lio	1	Redundant engine instru- ments provides adequate info.
			Conclusion	: OK.					

Conclusion: Far £3 requires pitch trim indicator. (Included in basic instrumentation) uAAS provides additional info. to alert the pillot if the A/C status is ok. It is assumed that the today used pre flight check routines will be followed. (If not, the DAAS may introduced new failure modes.)

145

of plon	ON ONE

FAILURE NO.	DAAS ELEHENT	NO.	FAILURE	FAILURE RATE*106	AFFLCTED ELEMENTS	LFFECTS OF FAILURE	DAAS WARHLETC.	FAILURE CATEGORY	Certais
42	LmS - Switch and related logic	Control Wheel	Failed Switcn	5	A/P - CPU Clutches	CMS-Mode Engaged accidently.	tto	3	AIP and nold modes disengaged without pilot awareness. No info.
			Conclusion	` pilot b	y monitoring th	te means to disengage the A/P. e instruments will detect a no cont. wheel steady when releas	t desired CWS-		
43	to-Around Switch	Control Wheel	Failed Switch	4	A/P - CPU	Go-around mode engaged accidently.	но	2	Information given on the annunciator panel.
						Go-around mode not engaged when wanted.		3	Demanding woments to the pilot, especia ly if in the A/P-Appr/65 mode.
			Conclusion			not is available when needed a situation. (4-4-10-6 x ?,low			у
44	Eng./wisen- gage-Switch	Lontrol श्रीख्थी	Failed Switch	4	A/P - CPU Triu Notor	Disengage of A/P-modes accidently.	llo	2	Annunced!
	Pitch Trim	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				Only Aut. Trim available		2	Use AutoTrio
45	neep-Trim	Control		4	A/P - CPU	No Hanual Trim		2	use AutoIrim
	Pitcn	Hiteel	Switch		Triu Hator	Run-away Trim		3	tse AutoIria
			Lonclusion	: The A	utoTriw functi	on replaces Manual Trim in A/P	wodes.		
40	Autopilot Damp Switch and kela,	iontrol dicel	Failed Switch	4+4	A/P - CPU Clutches	Disengage of A/P modes accidently.	ilo	2	Amunicell
						dot possible to disengage MP.		3	behanding in an A/P failure situation over power

Conclusion:

The probability for this situation involves both a switch failure and failure is another flight safety critical element. Estimated probability x ~ (4-8-10-6 x 4-1060-10-6)~1-10-7, ex.

FAILURE NO.	DAAS ELEMENT	NO.	FAILURE	FAILURE RATE*106	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARN. ETC.	FAILURE CATEGORY	COMENTS
47	Lonnunication Transceivers Antennas	KY- 195	Faulty Kadio	330	Communication Aids	No communication	34 G	1	Assumed Far 91 rules followed.
			Conclusion	DAAS h	as 3 systems, inc ication due to fa	ay radio communications system luding antennas. The probabi ulty transceivers is for DAAS 60-10 ⁻⁶ fault/FLT hour). OK.	lity of loss o (4-330-10 ⁻⁶) ²	f	-6 _. -5-10 ⁻⁸
48	Navigation Receivers Antennas	KN- 53	Faulty VOR	250	Radio Adpt. Box NAV-CPU EISI - RMI Radio Adpt. Box NAV-CPU ENSI - ADI	No or faulty VOR/GS	No	2	Traffic control support radar vectoring etc. uRus dead-reckoning.
			Conclusion	and di	al 10C/GS - recei	late single channel navigation ving systems and a FC-guidance eceivers and duplex-antennas,	e system for C	at X condit	ions.
49	DHL receiver antenna	K11- 62A	Faulty keceiver	500	Regio Adapt. Box NAS-250 LHSI	Faulty Havigation Info.	Но	2	Fault detected "Malman- Wind" etc. YOR available.
			Conclusion	n: Far 91	requires DHE if	flying at and above 24000 fee	t. Separate a	ntenna. OK	•
υc	Transponder Antenna	KT- 76a	Faulty Transpond	400	Radio Adapt. box	No Identification possible	No	1	Traffic control takes proper action.
			Conclusion	The pi	l do not require t robability for a f ilected. Separate	afture giving information pos	sible to misin	terpret by	traffic control

FAILURE No.	DAAS ELEHENT	w.	FAILURE	FAILURE RATE*10 ⁶	AFFECTED ELEMENTS	EFFECTS OF FAILURE	WARN. ETC.	FAILURE CATEGURY	CUMMENTS
51	Audio headsets	КНА-24	Fault in receiving parts	200	Earsets, speakers microphones	No audio info. Talk, Nav. CM MM	NO	3	ć
			Fault in transmit parts		arcrophones	No cutgoing talk		•	One-way comm possible
		CONCLU	SION: FAE DAAS	provides 3	separate syste	nication system. (Single faile ms possible to connect to the p panel. Very good redundancy.	ilct or ecpil		
52	Switch NAV 1 SEL		Stuck in		NAV-CPU NAVI - RECEIV	Only one of manual or DAAS control available.	NO	2	Assumed to create a confusing situation before
53	" NAV z SEL		" "	4	NAV-CPU			1	the pilot finds out how
	" DATE CET			_	NAV2-RECEIV	" " "	NG	2	a fault affects DAAS
54	" DATE SEL		" "	4	nav-cpu Dre receiv	Only one of NAV 1, 2, or DAAS control available	NO	2	function, and how he has to set the switches for
55	" VOR SEL	RMI	0 0	4		Only VOR 1 or 2 or none of VOR 1.2 avail. on RMI	NO	1	correct system operation.
56	" LOC/GS SE	L ADI	11 17	4	Radio adpt. box ADI	Only LOC/GS info. from NAV 1 or NAV 2 or what DAAS selects avail. on ADI	Ю	2	
		CONCLU			do not represe Co-pilot backu	nt single point failures in cri P-	tical single		
57	IDCC keyboard & touch P.		Faulty in- puts to IDCC	50	IDCC, CPU NAV-CPU EHSI	Erroneous fit. plan, flight status, way points, map, etc.	NO/YES	3	Keyed in messages dis- played on IDCG before entered. Detectable.
58	IDCC Selector sw	itches	Faulty mode selec	40 tion	IDCC, CPU	Wrong & not changeable "pages"	' но	2	Not wanted mode selected 6 not possible to select desired mode.
59	IDCC CPU, refrest memory & display	h-	Faulty computatio & presen-		IDCC, CPU	Wrong or garbeled info. displayed, not under- standable	YES BITE	2	Pilot misses 100 AID. Pilot detects the failure.
		CONCLU	in t	his respect	! The BITE det	not detecting "No 57 errors" ects about 80% of all computer -4-10 = 3-10-4 to 0.2-3-10-4	failures, shi	ch reduces the proba	
60	EHSI Selector su	itches	Faulty mode selection	20	EHSI-CPU EHSI	Wrong & not changeable modes or scales.	80		Not possible to select desired mode.
61	EHSI, CPU & BIH, refresh-memory and		Faulty computation		"	Wrong or garbled info. displayed	YES BITE	2	Pilot misses EHSI info. Fault detect possible by pilot.
	display	The pos	presentati obability f ssibility o cuverage.	or loss of	EHSI is∼400•4 ration (BIM + C	$^{-10}$ - 1.6·10 ⁻³ per 4 flt. hrs FU) reduces the probability to	4-325-10 ⁻⁶ •	• 1,3*10 ⁻³ essuming	1052

FAILURL NO.	DAAS ELEHERT	no.	FAILUR		LURE E*10 ⁶	AFFECTED ELEMENTS	EFFECTS OF FAILURE		DAAS WARM. ETC.	FAILURE CATEGORY	CUHLIS
		CONCL			ilities	makes DAAS OK.				situation very muc s to 15*10 ⁻⁶ per f	
52	Annunciator panel & drive circuits	KAP- 315	Fault panel driv.	or		Annunciator panel	Missed or wrong info.	mode status	Ю	2	Might temp. mislead the pilot. FC and NAV instruments will tell the truth, how-
		CONCL		FAR 23.1 mode is OK in th	engaged	. Switch posit	inform the pilot ions are not acce	what A/D -NA ptable. DAAS	v.		ever.
63	Mode controller and drive cir- cuits	кнс- 340	Faulty or hdg knob	trim 60 sel.		A/P-CPU various parts of DAAS	No trim/hdg sel Trim/hdg sel act accidentally.		Ю	2	The pilot overrides and disengages the system.
64	n		Faulty gle sw	tog- 18	0	11	Engage not vante Disengage vanted Not defined mode ATT+>ALT)	mode		2	Demanding if a mode change takes place at busy part of the flight, or a mode just quietly opens up.
65	16		Faulty oid sw	solen- itches	100	"	Accidental engag gage of A/P (Y/D			2	
		CONCLI	USION:	FAR 23 r	equirem	ent on accessib	llity of controls	met. OK.			
66	Auto pilot yaw clutch, serv	10	Fault hardwa	in any 7 re	0	Control surface	Servo not mova Servo run away locking clutch locked	clutch not	Ю	2	No Y/D avail. Filot override Disengage Y/D
67	Roll Clutch, ser	cvo	II.	71	0	n	n	4+	ю	3	No roll A/P avail. Pilot override Disengage A/P.
68	Pitch clutch, se	rvo	••	7(0	H	**	"	. 100	3	No pitch A/P avail. Pilot override. Disengage A/P.
69	Trim clutch, ser	rvo	11	50	0		Trim not moves Trim run sway	ble	Yes Trim monitor	3	Monitor detects trim runsways open circuit- ries, but not motor failures (e.g., only one direction.)
70	Clutches common logic		Faulty circui			Control sur- faces	None of the cl gages. All cl stay engaged.		NO	3	No A/P engaged. Pilot must override in 3 axes.

AILURE NO.	DAAS ELEMENT	но.	FAILURE	FAILURE RATL*10 ⁶	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARN. ETC.	FAILURE CATEGORY	CUTELITS
		CONCL	or al	e pilot migh perational. Il 3 servos. f not being d	it end up in a No warning or The probabili ble to disenga	lities to override. FAR 23 critical situation if one or info given. The pilot is in ty of not being able to engage all clutches is ~ (4.5-10 is situation is negligible!	more of the serve a critical situates in the serve all clutches in the	os or of the clu tion if he has t a ~ 10-4/4 her	utches are not
71	A/P-I/O CPU + BIM A/D, D/A, MUX		Fault in hardware		Almost all elements:	Erroneous: Mode status F/D-commands servo-commands Flt warning cruise-perform. fuel distance	YES BITE BITE	3	The A/P-I/O computer is a key element in DAAS. Faifure effects of all categories may occur. For instance, a CPU failure may
A11	ERAL POSSIBLE FAIL signals high or i zer faul arate signals	ow os	DES MUX	A/D CPU MEP x x x x x x	ORY D/A MUX	IDDC info ENSI map Annunciator Error may affect only one function,	}		affect separate in- structions, e.g. shi? which will spoil all mult. and div. A D/A failure may cause all outputs to go high
						e.g., door warn- ing, or many elements, e.g. D/A failure commanding 3 servos hardover.	}	1 3	including all servos and ADI command bars.
	The bite coverag requested to bri	e is a ng the	bout 95%. probabili	It is very ty of an und	likely that Bi etected failure	TE will detect even more of e down to 10 ⁻⁶ /4 hrs.	the severe failu	res. A BITE cou	errage of 99.9% is
		CONCL	FA de wi	R Z3 require tected .or n 11, in such	ment on only a ot by the BITE, situations, tak	nger or and possibility to o ing's axix hardover failure vill cause transients and s over and DAAS will be disc	ie violated. It shut down najor p	is probable tha	t failures occur which,
70	11112 F1 T / Or Av					nflict is recommended.			
72	NAV FLT/PLAN CPU & BIM		Fault in any hard ware		A/P comm. bar A/P servos EHSI IDCC NAV 1, 2 BUBBLE MEM.	Erron. comm. references Faulty map Faulty NAV info. Wrong frequencies Store faulty NAVAID data	YES BITE	2	Undetected erroneous NAV computations may, during a fairly long time, introduce A/C position errors. Sever indicators may give co sistently faulty info. Loss of NAVAID after a detected fault may als

bring problems to an unexperienced pilot.

CONCLUSION: The probability of faulty NAV calculations is ~ 4.72·10⁻⁶ ~ 3·10⁻⁴ without reconfiguration.

The probability of faulty NAV calculations is ~ 4.72·10⁻⁶ (1-\frac{80}{100}) + (4.72·10⁻⁶)² . (1-\frac{20}{100}) ~ .6·10⁻⁴ with reconfiguration.

Reconfiguration improves the availability of the NAV calculations 5 times. Significant improvements requires better BITE coverage.

DAAS with co-pilot OK.

ORIGINAL FROM TO OF POOR QUALITY

488 Bus

NO.	DNAS ELENENT	w.	FAILUKE	FAILUKL RATE±IJ6	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARIL ETC.	FAILURE CATLGURY	Currents
73	SPARE CPU & BIM	÷	Fault in any parts	60 + 12	EHSI or by NAV computer controlled elements	Same failure effects as fault 61 EHSI, CPU, and 72 NAV CPU.	YES BITE	2	Similar to faults No. 61 and 72.
		CONCLU	fail (72	ures are r + 72)•4•10	that any spare equired, the property of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control		the DAAS perf IL + ERSI FAI	ormance is negl L) • (SPARE FAI	igible. Because 2 similar L) or
74	Radio Adapter Box & BIM	KRC	Fault in any part	40 + 12	EHSI IDCC A/P (ADI)	Mistune NAV/DME receiv. Garble NAV data to NAV A/P CPU, which may affect visual indicators and bugs as well A/P servos.	YES BITE	3	The failure effects are dependent on engaged moder e.g. during a coupled landing the DAAS may control all indicators (excet the RMI) as well as the A/P servos and ADI bugs.
		CONCLU	SION: The	co-pilot b	ackup NAV instr	umentation makes DAAS OK.			_
75	DABS - CPU + BIM Panel		Any part failure	60 + 12	IDCC	No identification possible	YES BITE	1	No readable output Traffic control takes proper action.
	Transponder	CONCLU		ALSO FAULT NOT FULLY	NO. 50 KT-76A	Misleading IDCC info presented to the 1 pilot TRANSPONDER.			
76	Bus controller and reconfig. CPU + BIM		Any part failure	60 + 12	All DAAS computers & functions	Power up mode. One or more faults in one or more of the CPU's when loading the pro- grams	YES BITE	1	These failures are expected to be detected by BITE or the pilot.
						Normal Hode 1. Hisinterpretation of vali- signals and shutdown of fa		3	These failures might resu in a demanding situation they occur during a busy flight phase.
						No warn. given for some BU IDCC-CPU failures.	US-CPU and	3	
						 Bus control failures may in missed information or plete bus traffic breakdom 	COM-	3	Loss of most of the DAAS functions in a busy fligh phase is demanding.
						Reconfiguration Mode The CPU may fail to recon figure.	-	2	Results in loss of EHSI or NAV computer.

Faults in 1 EQUAL TO BUS CONTROL FAILURES NO. 76 wires or conmectors

CONCLUSION: Failures in the bus controller may affect more than 1 channel. The DAAS co-pilot provides backup, making DAAS OK.

FAILURE NO.	DAAS ELEMENT	ııv.	FAILURE	FAILURE RATE*106	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WARII. ETC.	FAILURE CATEGORY	COMENTS
78	Bubble Mem.		Any part failure	300	All DAAS computers and func- tions	All kinds of failures might occur from single instruction failure to all CPU instruction faulty.	s in the CPU [*] s		A fault happening before flight will be detected by the mem. sum. check or uy the pilot before takeoff. £ failure during flight followed by a temp. rower loss may, in a worse case, mean loss of the DAAS.
		CONCLUS	is to the	bubble memo: the flight. probability	ry failure in a: The probabili y for critical	l channel may happen, FAR 23 vio ir, followed by a temporary powe ty for this to happen is estimat failures to occur due to the bub ive the FAR conflict.	r loss during ed at less tha	a demanding pha in (360-4-10-6)	x (50-4-10 ⁻⁶)~2-10 ⁻⁷ .
79	Cassette		Any part failure	500	Bubble memory	The failure effects are simila to bubble memory failures.	r YES CPU mem. sum. check	3	A fault will be detected before flight.
		CONCLUS	ION: Cas:	sette failu sette failu	res will very li re is judged to	ikely be detected by BIT or the be $<10^{-6}$. DAAS OK.		akeoff. The pr	obability of an undetected
80	Alternator (Batt.) 28VDC bus		Alternato: Battery, l failures		All electrical units except DAAS-buses	I Shuts down all major DAAS sensors.	Obvious	4	Very critical situation.
		CONCLUS	It :	ls assumed I	that the pilot o	on avionics el. power bus redund quickly disengages a faulty A/C the 28 VDC bus during 4 flt, hrs att. + \(\int \text{bus} \simeq (200-4-10^5)^2 \) x (battery if it	fails when any	alternator is OK.
			NOTE	E: The batt	tery will be dra	sined in less than 1 flt. hr. (the most likely reason for elec	Before the bat	tery is drained	l, the probability of
81	Avionics bus 28 VDC		Connection switches l	ns, ~.।	Audio NAV, DME, X-ponder, etc.	Loss of communication.	NO	4	Affects both the pilot and co-pilot commun. NAV equipment.
		CONCLUS			lines and switch	nes make the avionics bus as saf tation electrical power should,			
82	DAAS A and B 28 VDC bus		Connection switches, diods, bat buses	• -	DAAS CPU's memories, ENSI, IDCC, FCS, etc.	Shuts down DAAS	YES BITE	3	Reliability degradation is due to single switches and lines.
		CONCLUS	ION: DAAS	with co-p	llot, demanding	3. Still low probability of el	ectrical power	loss:	
83	DAAS bus 115 and 26 VAC		Lines, switches, converters	10	DIR & vert. gy ADI, RMI, ADC sign condit.	rro Errors or no attitude refer- ences, etc.	YES "Validity"	3	
		CONCLUS	ION: Loss	of DAAS-A	AC judged OK.				

OF POOR	ORIGINAL
QUALITY	Page 13

FAILURL NO.	гунд	LLLHLHT	нu.	FAILURE	FAILUPL RATE*10 ⁶	AFFECTED ELEMENTS	EFFECTS OF FAILURE	DAAS WAKN. ETC.	FAILURL CATEGURY	CONTENTS
84	DAAS	15VDC		Lines switches inverter	15	ANALOG I/O	Most sensor inputs missing.	YES BITE	3	
85	DAAS	12VDC		"	18	Bubble Hem.	Reconfiguration not possible.	NO	3	Probability of reconfiguration low.
86	DAAS	SVDC		11	15	IDCC CPU's	Shut down of DAAS	Obvious	3	
	CONCLUSION: Failures 84 and 86 can be accepted in DAAS due to the co-pilot backup. FAR 23 is not met for electrical power failures 82 to 86. Actions are recommended.									
ADDITION	DAAS	S Soft-	ALL.	CPU¹s	unknown	A/P, servos, EHSI, IDCC, e		. NO	3	
			CONCL	USION: The	DAAS co-pil	lot will take or	ver and DAAS will be disengaged.	. ok.		